

RECEIVED  
14 NOV 2013

## Schedule 6 - Notification

These pages outline the information that the operator must provide.

Units of measurement used in information supplied under Part A and B requirements shall be appropriate to the circumstances of the emission. Where appropriate, a comparison should be made of actual emissions and authorised emission limits.

If any information is considered commercially confidential, it should be separated from non-confidential information, supplied on a separate sheet and accompanied by an application for commercial confidentiality under the provisions of the EP Regulations.

### Part A

Permit Number	BR9383ID	Notification Reference	EP_EX_120
Name of operator	Knauf Insulation Ltd		
Location of Facility	Chemistry Lane, Queensferry, Deeside, Flintshire, CH5 2DA		
Time and date of the detection	On the morning of 14 <sup>th</sup> November 2013		

<b>(a) Notification requirements for any malfunction, breakdown or failure of equipment or techniques, accident, or fugitive emission which has caused, is causing or may cause significant pollution</b>	
<b>To be notified within 24 hours of detection</b>	
Date and time of the event	13 <sup>th</sup> November 2013 at 20:14 to 20:24 and 20:36 to 20:45
Reference or description of the location of the event	Emergency By-Pass Stack (Emission Point B)
Description of where any release into the environment took place	Two incidences from the emergency by-pass stack encompassing a ten minute period and a nine minute period.
Substances(s) potentially released	Particulate, Carbon Monoxide, Nitrogen Oxide as NO <sub>2</sub> , Sulphur Dioxide, Hydrogen Sulphide.
Best estimate of the quantity or rate of release of substances	522kg of CO; 3.6kg of SO <sub>2</sub> ; 2.7kg of Particulate; 0.3kg of NO <sub>x</sub> ; 0.1kg of H <sub>2</sub> S.
Measures taken, or intended to be taken, to stop any emission	At the time of the release the burner was re-lit and normal operation was restored as quickly as practical. The burner was shut off, apparently by a temperature safety limit; the cause of the temperature trip-out will be investigated and appropriate action taken to prevent recurrence.
Description of the failure or accident.	Following process start up on the evening of 13 <sup>th</sup> November, the cupola abatement oxidiser burner was shut off, apparently by a temperature safety limit; the emergency stack opened for a period of ten minutes with the blast air continually fed to the furnace to prevent freezing and avoid a complete re-start. The by-pass was closed for approximately twelve minutes; however, the by-pass re-opened and remained open for a further nine minutes. This resulted in a release of unabated substances to atmosphere. The periods were minimised by maintaining blast air flow to the furnace and re-lighting the burner as quickly as was possible.

	INITIALS	DATE
OK FOR PUBLIC REGISTER	AS	21/11/13
COPIED TO PUBLIC REGISTER	JB	EORM

<b>(b) Notification requirements for the breach of a limit</b>	
<b>To be notified within 24 hours of detection unless otherwise specified below</b>	
Emission point reference/ source	
Parameter(s)	
Limit	
Measured value and uncertainty	
Date and time of monitoring	
Measures taken, or intended to be taken, to stop the emission	

<b>Time periods for notification following detection of a breach of a limit</b>	
<b>Parameter</b>	<b>Notification period</b>

<b>(c) Notification requirements for the detection of any significant adverse environmental effect</b>	
<b>To be notified within 24 hours of detection</b>	
Description of where the effect on the environment was detected	
Substances(s) detected	
Concentrations of substances detected	
Date of monitoring/sampling	

<b>Name*</b>	Claire Hensley
<b>Post</b>	Environmental Manager
<b>Signature</b>	<i>C. Hensley</i>
<b>Date</b>	14 <sup>th</sup> November 2013

\* authorised to sign on behalf of Knauf Insulation Ltd

