

		NETWORK RAIL Detailed Examination - Culvert										
Report Type: Detailed Examination - Culvert												
ELR: SWM2		Contract Mileage: 239m 0264yds 12.00chs					Struct Ref: 239 12					
Struct Type: B/C					OS Ref: SN370111							
Exam Type: Detailed					Rpt ID: [xxxxxxx]							
Structure Name: 5' stone arch with tidal flap on downside						Route: Wales						
Area: Towy						Exam ID: 15608180						
Any Hidden Parts: Yes				Observed Under Load: Yes				Exam Date: * 12/09/2023				
SCMI Score: * [xxxxxxx]				SCMI Date: * [dd/mm/yyyy]				Complete Exam: Yes				
Structure Carries: Rail						Structure Over : Water						
Section A: To Be Completed By The Examining Organisation												
Hidden parts not examined (excluding foundations)		Part*				Reason*						
		Invert				Silt and water levels						
		Downside headwall				Tidal flap						
ITEM*	DESCRIPTION*	LOCATION	Est. Cost £ +/- 20%	Priority Within	Quantity	Severity	Probability	Risk Score Inc. Extent	Works Category			
1	Rake out and repoint areas of open joints and displaced brickwork (PR).	Culvert barrel	2000.0	1yr	9 m2	2	3	S 6	Hand Pointing			
2	Replace area of missing masonry (PR).	Low mileage abutment 4.3m from Downside end	1000.0	1yr	1 m2	2	3	S 6	Brickwork/Stone Repairs			
History of Live Significant Defects												
Defect ID	Description	Location	Exam Date	Access Gained*	Exam Type	Rec Raised	Risk Score*	Access Required*	Deterioration	Repaired*	Flagged For Closure	Engineer Comments
1	Displacement of up to 80mm, DOJ	Crown, 3.8m from Downside end, 0.5m2	03/10/17	Y	D	Y	6	Y	Baseline	N	N	Heavy maintenance will extend the life of the structure
1	Displacement of up to 80mm, DOJ	Crown, 3.8m from Downside end, 0.5m2	16/08/18	Y	V	Y	6	Y	Cannot Determine	N	N	No access
1	Displacement of up to 80mm, DOJ	Crown, 3.8m from Downside end, 0.5m2	17/07/19	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
1	Displacement of up to 80mm, DOJ	Crown, 3.8m from Downside end, 0.5m2	09/07/20	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
1	Displacement of up to 80mm, DOJ	Crown, 3.8m from Downside end, 0.5m2	24/06/21	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
1	Displacement of up to 80mm, DOJ	Crown, 3.8m from Downside end, 0.5m2	14/07/22	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
1	Displacement of up to 80mm, DOJ	Crown, 3.8m from	12/09/23	Y	D	Y	6	Y	N	N	N	NFD at exam.

		Downside end, 0.5m2										
2	Joints open up to 300mm, total area 8m2	Abutments	03/10/17	Y	D	Y	6	Y	Baseline	N	N	Heavy maintenance will extend the life of the structure
2	Joints open up to 300mm, total area 8m2	Abutments	16/08/18	Y	V	Y	6	Y	Cannot Determine	N	N	No access
2	Joints open up to 300mm, total area 8m2	Abutments	17/07/19	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
2	Joints open up to 300mm, total area 8m2	Abutments	09/07/20	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
2	Joints open up to 300mm, total area 8m2	Abutments	24/06/21	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
2	Joints open up to 300mm, total area 8m2	Abutments	14/07/22	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
2	Joints open up to 300mm, total area 8m2	Abutments	12/09/23	Y	D	Y	6	Y	N	N	N	NFD at exam.
3	Missing masonry 0.4m x 0.12m x 0,3m	LM abutment 4.3m from Downside end	03/10/17	Y	D	Y	6	Y	Baseline	N	N	Heavy maintenance will extend the life of the structure
3	Missing masonry 0.4m x 0.12m x 0,3m	LM abutment 4.3m from Downside end	16/08/18	Y	V	Y	6	Y	Cannot Determine	N	N	No access
3	Missing masonry 0.4m x 0.12m x 0,3m	LM abutment 4.3m from Downside end	17/07/19	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
3	Missing masonry 0.4m x 0.12m x 0,3m	LM abutment 4.3m from Downside end	09/07/20	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
3	Missing masonry 0.4m x 0.12m x 0,3m	LM abutment 4.3m from Downside end	24/06/21	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
3	Missing masonry 0.4m x 0.12m x 0,3m	LM abutment 4.3m from Downside end	14/07/22	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
3	Missing masonry 0.4m x 0.12m x 0,3m	LM abutment 4.3m from Downside end	12/09/23	Y	D	Y	4	Y	N/A	N	N	NFD at exam.
4	Loose masonry including one missing block	Down LM wing wall	03/10/17	Y	D	Y	6	N	Baseline	N	N	Grouting
4	Loose masonry including one missing block	Down LM wing wall	16/08/18	Y	V	Y	6	N	N	N	N	No access
4	Loose masonry including one missing block	Down LM wing wall	17/07/19	N	V	Y	6	Y	NV	N	N	Unable to view at this exam; risk score unchanged
4	Loose masonry including one missing block	Down LM wing wall	09/07/20	N	V	Y	4	Y	NV	N	N	Not fully viewed but repairs appear to have been carried out, risk score reduced 2x2, confirm status at next DE
4	Loose masonry including one missing block	Down LM wing wall	24/06/21	Y	V	Y	4	Y	N	N	N	No change
4	Loose masonry including one missing block	Down LM wing wall	14/07/22	Y	V	Y	4	N	N	N	N	No change
4	Loose masonry including one missing block	Down LM wing wall	12/09/23	Y	D	Y	4	Y	Y	N	N	SSD at exam. Monitor at next exam.
5	PNE - Access, Vegetation, high water (tide) and tidal flap	Entire structure	16/08/18	N	V	Y	6	N	Baseline	N	N	Form safe access
5	PNE - Access, Vegetation, high water (tide) and tidal flap	Entire structure	17/07/19	N	V	Y	6	Y	NV	N	N	Clear vegetation to enable access
5	PNE - Access, Vegetation, high	Entire structure	09/07/20	N	V	Y	6	Y	NV	N	N	No change

	water (tide) and tidal flap											
5	PNE - Access, Vegetation, high water (tide) and tidal flap	Entire structure	24/06/21	N	V	Y	4	Y	NV	N	N	Detailed undertaken in 2017
5	PNE – No access due to vegetation on steep embankment and tidal flap	Barrel and upside headwall	14/07/22	N	V	Y	6	Y	NV	N	N	Upside accessed at 2017 exam, how vegetation on embankment has started to cause access issue on steep embankment
5	PNE – No access due to vegetation on steep embankment and tidal flap	Barrel and upside headwall	12/09/23	Y	D	Y	0	N/A	N/A	N/A	Y	Veg removed - close.

Examining Engineers Comments

None

Signed:



Name:* Mike Hirst

Date:* 31/10/2023



NETWORK RAIL



Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds 12.00chs

Struct Ref: 239 12

Struct Type: B/C

NR ID: auto
complete

Rpt ID: auto
complete

OS Ref: SN370111

Exam ID: 15608180

Dimensions: Length: 20m Diameter: 1.55m Cover: 2.5m

Exam Date: 12/09/2023

Primary Material: CUL - Stone

Last Detailed: 03/10/2017

Secondary Material: [xxxxxxx]

Last Visual: 14/07/2022

Structure Carries: Rail

Structure Over: Water


Line: SOUTH WALES MAIN LINE: GLOUCETSER YARD JCT TO JOHNSTON

Structure Name: 5' stone arch with tidal flap on downside

Elevation Photograph



Map Extract





NETWORK RAIL



Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds 12.00chs

Struct Ref: 239 12

Examiners General Comments:

CONSTRUCTION

SWM2 239 12 is a transverse culvert consisting of a stone arch barrel. The upside consists of a stone headwall. The downside consists of a stone headwall with timber tidal flap. The structure carries a watercourse beneath 2no lines at 239m 0264yds. Flow runs from upside to downside.

METHOD OF EXAMINATION

The structure was examined by Inspire Structures Ltd using CCTV equipment and hand tools during daytime working hours.

Access Data	
Method of Access	Comments
CCTV	COSS +1

CONDITION SUMMARY

The structure was found to be in generally fair condition during this examination.

I confirm that previous detailed examination and visual reports have been reviewed and the dates of said report are given in this report.

The last detailed examination was incomplete, and the unexamined parts are shown below: -

Downside Voussoir/Headwall – Due to Tidal Flap.

Has all of the structure been viewed?

No. Invert viewed at ends only due to silt and water levels within barrel. Downside headwall not viewed due to tidal flap.

Has the structure been viewed under load?

Yes.

Signed:

Examiners Name: Chris Rae

Date: 10/10/2023

		NETWORK RAIL Detailed Examination - Culvert			
ELR: SWM2		Contract Mileage: 239m 0264yds 12.00chs		Struct Ref: 239 12	
Element Status Table					
Element Name		Status		Condition	
Barrel/Bore		Examined		Fair	
Ballast Plates and Boards		N/A		N/A	
Bearings		N/A		N/A	
Cross Girders		N/A		N/A	
Floor/Deck		N/A		N/A	
Longitudinal Timbers		N/A		N/A	
Main Girders		N/A		N/A	
Parapets and Pilasters		N/A		N/A	
Rail Bearers		N/A		N/A	
Headwalls		Examined		Good	
Waterproofing		N/A		N/A	
Abutments		N/A		N/A	
Bedstones and Cills		N/A		N/A	
Columns and Cylinders		N/A		N/A	
Piers		N/A		N/A	
Trestles and Crossheads		N/A		N/A	
Wing and Retaining Walls		Examined		Fair	
Clearances		N/A		N/A	
Coping and Cappings		N/A		N/A	
Debris		N/A		N/A	
Drainage		Examined		Fair	
Foundations		N/A		N/A	
Invert		Not Examined		Cannot Determine	
Handrails		N/A		N/A	
Painting		N/A		N/A	
Pointing		Examined		Poor	
Revetment Walls		Examined		Poor	
Rivets and Bolts		N/A		N/A	
Signage		N/A		N/A	
Track/Road		Examined		Good	
Vegetation		Examined		Fair	
Monitoring Devices Present					
Date Tabs		No			
Plumb Points		No			
Avongards		No			
Environmental Factors Present					
Item Number	Description			Location	
[x]	N/A			[xxxxxx]	
Record of Observations Under Load (Bridges and culverts only)					
Load Type	General Area Observed	Result of Observation		Date and Time	
Multiple Units	Barrel	No movement noted		12/09/2023	
Comments	[xxxxxx]				

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds 12.00chs


Struct Ref: 239 12

DESCRIPTION AND MATERIAL

SWM2 239 12 is a transverse culvert consisting of a stone arch barrel. The upside consists of a stone headwall. The downside consists of a stone headwall with timber tidal flap

DIMENSIONS

	A	B	C	D	E	F
End of Culvert	+/- 1m	+/- 100mm	+/- 100mm	+/- 100mm	+/- 100mm	+/- 10mm
UP side	4 m	2500 mm	1600 mm	1550 mm	200 mm	450 mm
DOWN side	3 m	4000 mm	1600 mm	1550 mm	0 mm	0 mm



Can detailed exam be undertaken in due year?	Yes	Invert not viewed due to silt and water levels.
Direction of flow:	Up to Down	[xxxxxx]
Watercourse functional?	Yes	[xxxxxx]
Approach ditch functional?	Yes	[xxxxxx]
Depth of water	150 mm	[xxxxxx]
Depth of silt	100 mm	[xxxxxx]
Length of culvert	20 m	[xxxxxx]
Lack of airflow?	Yes	[xxxxxx]
Biological/toxic hazard/fumes?	No	[xxxxxx]
Confined spaces?	Yes	[xxxxxx]
Services in culvert?	No	[xxxxxx]
Do services prevent of restrict examination of culvert?	No	[xxxxxx]

		NETWORK RAIL Detailed Examination - Culvert				
ELR: SWM2		Contract Mileage: 239m 0264yds 12.00chs		Struct Ref: 239 12		
DRAINAGE MANAGEMENT – Inspection and maintenance in accordance with NR/L3/CIV/005						
Please score (0 to 5) the serviceability state of the culvert – tick as appropriate						
SCORE	0	1	2	3	4	5
	☐	☐	☐	☒	☐	☐
Guidance	Not inspected due to access issues i.e. Vegetation preventing access.	Clear, no sediment in drainage, no obstructions, no debris on screen, minor accumulation of vegetation, no debris in catchpits	Superficial deposits, sediment <5% of cross section, superficial obstruction to flow, some sediment in catchpit but below pipe invert, light debris on screen, minor accumulation of vegetation	Performance slightly reduced, sediment <25% of cross section, minor obstruction to flow, catchpit full of sediment but not effecting flow, debris half way up trash screen, vegetation becoming established	Performance severely reduced, sediment levels between 25% and 75% of cross section, significant obstruction to flow, catchpit full of sediment and effecting flow, debris more than half way up trash screen, shrubs and large established plants	Blocked, sediment levels >75%, severe or complete obstruction to flow, catchpit full of sediment to above soffit, debris covering full screen, flow blocked or surcharging due to litter/vegetation
For culverts where the serviceable state scores ≥ 3, a recommendation for clearance must be raised. Please start this recommendation with “DRAINAGE AND OFF-TRACK – SCORE XX -”.						
Embankments – Actions for Safe Access						
Score	1		2		3	
Upside	☐		☒		☐	
Downside	☐		☒		☐	
Guidance	Shallow embankment, secure underfoot conditions. No specialist PPE / access equipment needed		Steep embankment (>45deg) and / or uneven / unseen underfoot conditions. However, a Dynamic Risk Assessment determines that on this occasion the embankment can be accessed using safe walking techniques and / or specialist access techniques.		Unsafe if ANY of the following criteria are met: - Steep embankment (>45deg) - uneven / unseen underfoot conditions. - Shale / slippery material - Unable to maintain and secure safe working level upon embankment - Unable to undertake a controlled descent	
	Safe Access		Proceed with caution		Unsafe Access	

	NETWORK RAIL Detailed Examination - Culvert	
ELR: SWM2	Contract Mileage: 239m 0264yds 12.00chs	Struct Ref: 239 12
STATUS OF PREVIOUSLY RECORDED SIGNIFICANT DEFECTS and STATUS OF RECOMMENDATIONS MADE AT PREVIOUS EXAMINATION <u>Defect No:</u> 1 <u>Description:</u> Displacement of up to 80mm, DOJ <u>Location:</u> Crown, 3.8m from Downside end, 0.5m² <u>Status:</u> NFD. Not actioned. <u>Recommendation From Previous Year:</u> Rake out and repoint areas of open joints and displaced brickwork. <u>Photo:</u> 15 <u>Defect No:</u> 2 <u>Description:</u> Joints open up to 300mm, total area 8m² <u>Location:</u> Abutments <u>Status:</u> NFD. Not actioned. <u>Recommendation From Previous Year:</u> Rake out and repoint areas of open joints and displaced brickwork. <u>Photo:</u> See barrel general photos. <u>Defect No:</u> 3 <u>Description:</u> Missing masonry 0.4m x 0.12m x 0.3m <u>Location:</u> Low Mileage Abutment 4.3m from Downside end. <u>Status:</u> NFD. Not actioned. <u>Recommendation From Previous Year:</u> Replace area of missing masonry. <u>Photo:</u> 13 <u>Defect No:</u> 4 <u>Description:</u> Loose masonry including one missing block <u>Location:</u> Down Low Mileage wingwall <u>Status:</u> SSD was 1m² now 2.5m². Missing masonry appears to have been repaired. <u>Recommendation From Previous Year:</u> None. <u>Photo:</u> 32 <u>Defect No:</u> 5 <u>Description:</u> PNE – Access, Vegetation, high water (tide) and tidal flap. <u>Location:</u> Barrel and upside headwall <u>Status:</u> Vegetation cleared prior to exam. Compliant DE conducted utilizing CCTV equipment. Actioned. <u>Recommendation From Previous Year:</u> Clear vegetation and treat to prevent regrowth to allow access at future exams (provide access steps if deemed required after removal to allow safe access). <u>Photo:</u> See report for details.		
OTHER RECOMMENDATIONS MADE BY THE ENGINEER ON LAST REPORT None.		
STRUCTURE DIMENSIONS See Data Sheet.		
GENERAL PHOTOGRAPHS P1 – Upside Elevation P2 – Downside Elevation P3 – Upside Barrel view P4 – Downside Barrel view P5 – Upstream view P6 – Downstream view P7 – Track view Low to High Mileage P8 – Track view High to Low Mileage P9 – Track view Upside to Downside		
SUMMARY OF ELEMENTAL PARTS Culvert Barrel – Fair Condition Stone construction. 20m long.		

Defects measured from Upside (0m):

@2.2m in crown, Transverse Fracture open approx. 2-4mm wide x 3.1m long. NEW. See P10.

----- @4m Approx. Upside Cess Rail Position -----

@6m, Longitudinal Fracture open approx. 3mm wide x 1m long. NFD. See P11.

@9.3m in crown, area of stonework displaced down by approx. 25mm x 100mm wide x 2m long. NFD. See P12.

@13.5m in Low Mileage sidewall, 1no missing stone. NEW. See P13.

@16.3m, Longitudinal Fracture open approx. 1-3mm wide x 1m long. NEW. See P14.

@17m in crown, area of stonework displaced down by approx. 15mm x 0.5m² total area. NFD. See P15.

----- @17m Approx. Downside Cess Rail Position -----

@20m end of culvert

Culvert Barrel General Comments:

Throughout barrel, open joints to typically approx. 60mm deep, max 250mm deep x 15m² total area. NFD. See barrel general photos.

Culvert Barrel General Photos:

Culvert barrel general view @0m. See P3

Culvert barrel general view @5m. See P16

Culvert barrel general view @10m. See P17

Culvert barrel general view @15m. See P18

Upside Headwall – Good Condition

E: 237067, N: 211163. Stone construction. See P19.

No significant defects noted at time of exam. See P19.

Downside Headwall – Cannot Determine

E: 237049, N: 211170. Not viewed due to tidal flap. See P4.

Throughout tidal flap. Algae staining to front of tidal flap. See P20.

Bolts to tidal flap are secure at time of exam. See P21.

Metallic fillet to topside of tidal flap has been replaced. See P22.

To wall above tidal flap, vertical fracture open HL-1mm wide x 300mm long. NEW. See P23.

Upside Low Mileage Wing Wall – Fair Condition

Stone construction. See P24.

Defects measured from upside headwall:

@0.6m, diagonal step fracture open 1mm wide x 2.1m long. NEW. See P25.

@1.5m, diagonal step fracture open 2-4mm wide x 2.4m long. NEW. See P26.

Throughout wingwall, open joints to typically 20mm deep, max 240mm deep x 1m² total area. NEW. See P27.

Upside High Mileage Wing Wall – Fair Condition

Stone construction. See P28.

Defects measured from upside headwall:

At offside end of wingwall, area of missing stonework to 400mm deep x 400mm wide x 420mm high with 1no stone displaced forwards by 25mm. NEW. See P29

Throughout wingwall, open joints to typically 40mm deep, max 60mm deep x 2.5m² total area. SSD was 0.75m². See P30.

Downside Low Mileage Wing Wall – Fair Condition

Stone construction. See P31.

Defects measured from downside headwall:

Top section, area of stonework is LTH to 2.5m² total area. SSD was 1m². See P32.

Top section at offside end, area of stonework displaced forwards by 20mm x 1m² total area. NEW. See P33.

Throughout wingwall, open joints to typically 70mm deep, max 100mm deep x 1.5m² total area. NEW. See P34.

Downside High Mileage Wing Wall – Fair Condition

Stone construction. See P35.

Defects measured from downside headwall:

Throughout wingwall, open joints to typically 50mm deep, max 100mm deep x 1m² total area. SSD was 0.25m². see P36.

Drainage – Fair Condition

Watercours is clear with a steady rate of flow at time of exam. See barrel general photos.

Invert – Good Condition

Where viewed, no significant defects noted at time of exam. See P37 and P38.

Pointing – Poor Condition

See barrel and wingwall sections for details.

Upside Low Mileage Revetment Wall – Poor Condition

Stone construction. See P39.

Dry stone revetment wall has collapsed at time of exam. NEW. See P39.

Upside High Mileage Revetment Wall – Poor Condition

Stone construction. See P40.

Dry stone revetment wall has collapsed at time of exam. NEW. See P40.

Track – Good Condition

CWR on concrete sleepers with no deformation noted at track level when viewed from a position of safety. See P7, P8 and P9.

Vegetation – Fair Condition

Vegetation cleared from structure prior to exam. See P1 and P2.

Detailed Examination - Culvert


ELR: SWM2

Contract Mileage: 239m 0264yds 12.00chs

Struct Ref: 239 12

SITE LOCATION SKETCH

SWM2 239 12 Site Location sketch N.T.S



Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 1

Description*: Upside
Elevation

Date: 12/09/2023

Type: General

Link: [xxxxxxx]



Photo Index*: 2

Description*:
Downside Elevation

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 3

Description*: Upside
Barrel view

Date: 12/09/2023

Type: General

Link: [xxxxxxx]



Photo Index*: 4

Description*:
Downside Barrel view

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 5

Description*:
Upstream view

Date: 12/09/2023

Type: General

Link: [xxxxxxx]



Photo Index*: 6

Description*:
Downstream view

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 7

Description*: Track
view Low to High
Mileage

Date: 12/09/2023

Type: General

Link: [xxxxxxx]



Photo Index*: 8

Description*: Track
view High to Low
Mileage

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 9

Description*: Track
view Upside to
Downside

Date: 12/09/2023

Type: General

Link: [xxxxxxx]



Photo Index*: 10

Description*: @2.2m
Transverse Fracture

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 11

Description*: @6m
Longitudinal Fracture

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]



Photo Index*: 12

Description*: @9.3m
Displacement

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 13

Description*: @13.5m
Missing Stone

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]



Photo Index*: 14

Description*: @16.3m
Longitudinal Fracture

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 15

Description*: @17m
Displacement

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]



Photo Index*: 16

Description*: Barrel
general view @5m

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence

10M_



Photo Index*: 17

Description*: Barrel
general view @10m

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

15M



Photo Index*: 18

Description*: Barrel
general view @15m

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 19

Description*: Upside
Headwall

Date: 12/09/2023

Type: General

Link: [xxxxxxx]



Photo Index*: 20

Description*: Algae to
Tidal Flap

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 21

Description*: Tidal
Flap Bolts

Date: 12/09/2023

Type: General

Link: [xxxxxxx]



Photo Index*: 22

Description*: Repairs
to Tidal Flap

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 23

Description*: Downside Vertical Fracture

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]



Photo Index*: 24

Description*: Upside Low Mileage Wingwall

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 25

Description*: @0.6m
Diagonal Step Fracture

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]



Photo Index*: 26

Description*: @1.5m
Diagonal Step Fracture

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 27

Description*: Typical
Open Joints

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]



Photo Index*: 28

Description*: Upside
High Mileage Wingwall

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 29

Description*: Missing/
Displaced Stonework

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]



Photo Index*: 30

Description*: Typical
Open Joints

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 31

Description*: Downside Low Mileage Wingwall

Date: 12/09/2023

Type: General

Link: [xxxxxxx]



Photo Index*: 32

Description*: Loose Stonework

Date: 12/09/2023

Type: Defect

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 33

Description*:
Displaced Stonework

Date: 12/09/2023

Type: Defect

Link: [xxxxxx]



Photo Index*: 34

Description*: Typical
Open Joints

Date: 12/09/2023

Type: Defect

Link: [xxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 35

Description*:
Downside High Mileage
Wingwall

Date: 12/09/2023

Type: General

Link: [xxxxxx]



Photo Index*: 36

Description*: Typical
Open Joints

Date: 12/09/2023

Type: Defect

Link: [xxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 37

Description*: Upside
Invert

Date: 12/09/2023

Type: General

Link: [xxxxxxx]



Photo Index*: 38

Description*:
Downside Invert

Date: 12/09/2023

Type: General

Link: [xxxxxxx]

Detailed Examination - Culvert

ELR: SWM2

Contract Mileage: 239m 0264yds
12.00chs

Struct Ref: 239 12

Photo Evidence



Photo Index*: 39

Description*: Upside
Low Mileage
Revetment Wall

Date: 12/09/2023

Type: General

Link: [xxxxxx]



Photo Index*: 40

Description*: Upside
High Mileage
Revetment Wall

Date: 12/09/2023

Type: General

Link: [xxxxxx]