

Photos taken during inspection of permit Ref: AB0075401 on 16/05/19



Interceptor



Discharge point and inspection chamber



Discharge point flap and plinth