

## **REVIEW OF THE SPMP REPORT 2015 – REHAU LTD, PPC PERMIT BX6421IY**

### **Response:-**

Reference data for the SPMP was taken during March / April 2006, which was submitted to the Environment Agency on 27.06.06 additional monitoring during August 2008 showed no significant concentrations of pollutants. Ongoing monitoring is not required unless an emergency situations arises.

### **Corrective Action:-**

- a) No emergency situations have taken place since the original reference data was submitted.
- b) Boreholes BH301 – 304 were removed during the construction of the Raw Materials Warehouse, which was advised in our EP Variation Application (EA/EPR/BX6421IY/V002)
- c) The drainage plan from the site changed significantly with the construction of the new Raw Material Warehouse and hardstand to the rear of the site. The following drainage items were installed and continue to be operational :-
  - Oil / Petrol Interceptor
  - Envirovalve

### **Conclusions**

1. No emergency situations have taken place.
2. The installation of the oil / petrol interceptor together with the envirovalve provides a significant improvement in water course protection.