

 MORRISONS	Environmental Management System		
	NRW Schedule 5 Notification Form		
Document Reference: EM 04-001	Issue Number: 2	Issue Date: 21.07.15	Page 1 of 3

These pages outline the information that the operator must provide.

Units of measurement used in information supplied under Part A and B requirements shall be appropriate to the circumstances of the emission. Where appropriate, a comparison should be made of actual emissions and authorised emission limits.

If any information is considered commercially confidential, it should be separated from non-confidential information, supplied on a separate sheet and accompanied by an application for commercial confidentiality under the provisions of the EP Regulations.

PART A

Permit Number	EPR/VP3235HS
Name of operator	Farmers Boy (Deeside) Ltd
Location of Facility	Unit 105/106, Tenth Ave, Deeside In Park CH5 2UA
Time and date of the detection	25 th Feb 2016

(a) Notification requirements for any activity that gives rise to an incident or accident which significantly affects or may significantly affect the environment	
To be notified within 24 hours of detection	
Date and time of the event	25 th Feb 2016 8.30am
Reference or description of the location of the event	Fire inside one Smoker unit inside the factory
Description of where any release into the environment took place	Smoke emission through Smoker flue Water used to extinguish the fire – discharged to effluent plant
Substances(s) potentially released	Particulates (smoke) Water
Best estimate of the quantity or rate of release of substances	Smoke - lasted approx. 20 mins. Unquantifiable Water - Unquantifiable
Measures taken, or intended to be taken, to stop any emission	Fire did not extend beyond the Smoker unit and was contained within the unit at all times. Factory production was ceased during the event as a precaution for health and safety reasons, but returned within approx. 1.5 hrs of fire detection. Fire extinguished as soon as possible by Fire Brigade and area passed safe for production to re-commence in the Factory. Smoker unit is currently out of commission and being repaired with a view to being re-commissioned this week.
Description of the failure or accident.	Fire started on a Smoker that was not in use. Cause is still being investigated, but early indications are that it was due to an electrical fault.

 MORRISONS	Environmental Management System		
	NRW Schedule 5 Notification Form		
Document Reference: EM 04-001	Issue Number: 2	Issue Date: 21.07.15	Page 2 of 3

PART A *(continued)*

b) Notification requirements for the breach of a permit condition	
To be notified within 24 hours of detection unless otherwise specified below	
Emission point reference/ source	
Parameter(s)	
Limit	
Measured value and uncertainty	
Date and time of monitoring	
Measures taken, or intended to be taken, to stop the emission	


Time periods for notification following detection of a breach of a limit	
Parameter	Notification period

c) In the event of a breach of permit condition which poses an immediate danger to human health or threatens to cause an immediate significant adverse effect on the environment:	
To be notified within 24 hours of detection	
Description of where the effect on the environment was detected	
Substances(s) detected	
Concentrations of substances detected	
Date of monitoring/sampling	

	Environmental Management System		
	NRW Schedule 5 Notification Form		
Document Reference: EM 04-001	Issue Number: 2	Issue Date: 21.07.15	Page 3 of 3

PART B – to be submitted as soon as practicable

Any more accurate information on the matters for notification under Part A.	We believe the fire was started by damaged electrical wire in old wiring within the Smoker unit. Spark ignited gas coming from the burner. The Fire starved itself after we turned the gas supply off. Fire brigade connected hoses to water hydrant, but we are not sure how much water they used, if any. It is possible they used a small quantity for 'dampening down' the inside of the unit. Fire never extended beyond smoker unit.
Measures taken, or intended to be taken, to prevent a recurrence of the incident	We have identified 2 more of our machines that have the same burners (same type & age). To prevent any issues, all 3 old burners are getting replaced (including new wiring). The Smoker burner is in the process of replacement. The 2 Roaster burners will be replaced week commencing 07/03/16
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	As above
The dates of any unauthorised emissions from the facility in the preceding 24 months.	

Name*	Grzegorz Lewandowski
Post	
Signature	
Date	03/03/16

* authorised to sign on behalf of the operator

