

Project

Project Name 2 Sisters Remedial

Description

Start Date 19/06/2017

Table of Contents

Project Name
2 Sisters Remedial

Project Number:

Date:
19/06/2017

Scoring Summary	P-1
Project Information	P-2
Legend of Classification (Section)	P-3
Section: 1; LINE A - SWMH10	1
Section: 2; SWMH13 - PI1	3
Section: 3; LINE A - SWMH11a	5
Section: 4; SWMH10 - SWMH11a	7
Section: 5; FWMH4 - FWMH6	9
Section: 6; LINE A - SW04	15
Section: 7; SWMH7 - SWMH8	17
Section: 8; ESW15 - ESW14	19
Section: 9; ESW1 - ESW2	21
Section: 10; EDMH9 - SC12	23
Section: 11; EDMH10 - EDMH11	25
Section: 12; LINE Y - SWMH14	28
Section: 13; LINE B - FWMH3	30
Section: 14; LINE A - EFW03	32
Section: 15; MH4 - MH3	34
Section: 16; ESW6 - ESW7	36
Section: 17; SWMH14 - SWMH13	38
Section: 18; SWMH13 - SWMH12	43
Section: 19; SWMH12 - SWMH13	47
Section: 20; MH1 - MH2	51
Section: 21; FWMH6 - FWMH6a	53

Scoring Summary

Project Name :
2 Sisters Remedial

Project Number :

Date :
19/06/2017

Structural Defects

Section	Pipe Ref	Grade	Description
Acceptable Structural Condition			

Grade 3: Best practice suggests consideration should be given to repairs in the medium term.

Grade 4: Best practice suggests consideration should be given to repairs to avoid a potential collapse.

Grade 5: Best practice suggests that this pipe is at risk of collapse at any time. Urgent consideration should be given to repairs to avoid total failure

Service / Operational Defects

Section	Pipe Ref	Grade	Description
3	LINE AX	5	Obstruction from 12 o'clock to 12 o'clock, 95% height loss

Grade 3: Best practice suggests consideration should be given to maintenance activities in the medium term.

Grade 4: Best practice suggests consideration should be given to maintenance activity to avoid potential blockages.

Grade 5: Best practice suggests that this pipe is at a high risk of backing up or causing flooding.

Abandoned Surveys

Section	Pipe Ref	Description
All Surveys Completed		

Information

These summaries are based on the SRM grading from the WRC.

Project InformationProject Name
2 Sisters Remedial

Client's ref :

Contractor's ref :

Date:
19/06/2017

Description

Client

Company: Two Sisters Poultry Ltd
Contact:
Department:
Street:
City:
Phone:
Fax:
Mobile:
E-Mail:

Site

Company: Two Sisters Poultry Ltd
Contact:
Department:
Street: Industrial Estate Road
City: Llangefni LL77 7UX
Phone:
Fax:
Mobile:
E-Mail:

Contractor

Company: Aquasentry
Contact: Darren Todd
Department: General Manager
Street: Plover Road
City: Huddersfield
Phone: 07551154329
Fax:
Mobile:
E-Mail: dtodd@aquasentryes.co.uk

Legend of Classification (Section)

Project Name
2 Sisters Remedial

Project Number:

Date:
19/06/2017

1:

Brick: No Structural Defects
Pipe: No Structural Defects

Acceptable Structural Condition

2:

Brick: Minor cracking, Surface mortar loss, Spalling slight, Wear slight
Pipe: Circumferential crack, Moderate joint defects, Spalling slight, Wear slight

Minor collapse risk in short term but potential for further deterioration

3:

Brick: Total mortar loss without other defects, single brick displaced, Deformation up to 5%, Spalling medium, Wear medium
Pipe: Fractures with deformation up to 5%, Longitudinal cracking or multiple cracking, Minor loss of level, More severe joint

! Collapse unlikely in near future but future deterioration likely !

4:

Brick: Total mortar loss with deformation greater than 10%, Deformation up to 10% and fractured, Displaced/hanging brickwork, Small number of missing bricks
Pipe: Broken, Deformation up to 10% and broken, Fractured with deformation 5 - 10%, Multiple fractures, serious loss of level, Spalling large, Wear large

!! Collapse likely in foreseeable future !!

5:

Brick: Already collapsed, Missing invert, Deformation over 10% and fractured, Displaced/hanging brickwork and deformation over 10%, Extensive missing bricks
Pipe: Already collapsed, Deformation over 10% and broken, Extensive areas of fabric missing, Fractured with deformation over 10%

!!! Collapsed or collapse imminent !!!


Inspection Report

Section Number : 1	Date : 19/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : LINE AX
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SWMH10 < LINE A	US MH: LINE A
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length: 1.98	DS MH: SWMH10
Surface Cover:	Pipe Length:	DS Depth: 1.08

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height: 150 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:50	Position m	Code	Observation	MPEG	Photo	Grade			
Depth: 1.08 SWMH10 									
	0.00	ST	Start of survey	00:00:00		0			
	0.00	MH	Manhole: SWMH10	00:00:00		0			
	0.00	WL	Water level, 5% of sewer height	00:00:00		0			
	0.33	LC	Sewer lining changes/starts/finishes at this point: start of repair patch	00:00:13		0			
	1.33	LC	Sewer lining changes/starts/finishes at this point: end of repair patch	00:00:34		0			
	1.98	FH	Finish survey	00:00:51		0			
Depth:									
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 19/06/2017 - LINE AX

Section Number : 1	Survey Direction : SWMH10 ↑ LINE A	PLR : LINE AX	Client's Ref :	Contractor's Ref :
------------------------------	--	-------------------------	----------------	--------------------



LINE AX_1fbc1e05-b299-436a-9252-769fd5c77bff_20170620_114150_457.jpg, 00:00:13, 0.33m
Sewer lining changes/starts/finishes at this point



LINE AX_84deb483-3fef-402f-b2ed-e27d9877b0ef_20170620_114232_648.jpg, 00:00:34, 1.33m
Sewer lining changes/starts/finishes at this point


Inspection Report

Section Number : 2	Date : 20/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : SWMH13X
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SWMH13 ® PI 1	US MH: SWMH13
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth: 2.12
Location:	Total Length: 1.41	DS MH: PI 1
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height: 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:50	Position m	Code	Observation	MPEG	Photo	Grade																																										
Depth: 2.12 SWMH13  <table><tr><td></td><td>0.00</td><td>ST</td><td>Start of survey</td><td>00:00:00</td><td></td><td>0</td></tr><tr><td></td><td>0.00</td><td>MH</td><td>Manhole: SWMH13</td><td>00:00:00</td><td></td><td>0</td></tr><tr><td></td><td>0.00</td><td>WL</td><td>Water level, 5% of sewer height</td><td>00:00:00</td><td></td><td>0</td></tr><tr><td></td><td>0.37</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: START OF REPAIR PATCH</td><td>00:00:00</td><td></td><td>0</td></tr><tr><td></td><td>1.06</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: END OF REPAIR PATCH</td><td>00:01:03</td><td></td><td>0</td></tr><tr><td></td><td>1.41</td><td>FH</td><td>Finish survey</td><td>00:01:13</td><td></td><td>0</td></tr></table> Depth:								0.00	ST	Start of survey	00:00:00		0		0.00	MH	Manhole: SWMH13	00:00:00		0		0.00	WL	Water level, 5% of sewer height	00:00:00		0		0.37	LC	Sewer lining changes/starts/finishes at this point: START OF REPAIR PATCH	00:00:00		0		1.06	LC	Sewer lining changes/starts/finishes at this point: END OF REPAIR PATCH	00:01:03		0		1.41	FH	Finish survey	00:01:13		0
	0.00	ST	Start of survey	00:00:00		0																																										
	0.00	MH	Manhole: SWMH13	00:00:00		0																																										
	0.00	WL	Water level, 5% of sewer height	00:00:00		0																																										
	0.37	LC	Sewer lining changes/starts/finishes at this point: START OF REPAIR PATCH	00:00:00		0																																										
	1.06	LC	Sewer lining changes/starts/finishes at this point: END OF REPAIR PATCH	00:01:03		0																																										
	1.41	FH	Finish survey	00:01:13		0																																										
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade																																							
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0																																							

Section Pictures - 20/06/2017 - SWMH13X

Section Number : 2	Survey Direction : SWMH13 ↓ PI 1	PLR : SWMH13X	Client's Ref :	Contractor's Ref :
-----------------------	-------------------------------------	------------------	----------------	--------------------



SWMH13X_e7789cd4-cdb6-4824-87b5-772fc65de6b3_20170620_152211_616.jpg, 00:00:00,
0.37m
Sewer lining changes/starts/finishes at this point



SWMH13X_dd588aea-59b7-4d0f-a5c0-c70071613441_20170620_152341_569.jpg, 00:01:03,
1.06m
Sewer lining changes/starts/finishes at this point


Inspection Report

Section Number : 3	Date : 22/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : LINE AX
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SWMH11a < LINE A	US MH: LINE A
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 12.73	DS MH: SWMH11a
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height 150 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:108	Position m	Code	Observation	MPEG	Photo	Grade			
Depth: SWMH11a									
	0.00	WL	Water level, 5% of sewer height	00:00:00		0			
	0.00	ST	Start of survey	00:00:00		0			
	0.00	MH	Manhole: SWMH11a	00:00:00		0			
	4.19	F01	DES	Debris silt, 15% cross-sectional area loss, Finish	00:00:18		3		
	12.73	OB		Obstruction from 12 o'clock to 12 o'clock, 95% height loss	00:01:49		5		
LINE A	12.73	FH	Finish survey	00:02:08		0			
Depth:									
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0.0	0.0	0.0	1.0	2	10.0	0.9	12.0	5.0

Section Pictures - 22/06/2017 - LINE AX

Section Number : 3	Survey Direction : SWMH11a ↑ LINE A	PLR : LINE AX	Client's Ref :	Contractor's Ref :
------------------------------	---	-------------------------	----------------	--------------------



LINE AX_9a7fae94-dcd1-4566-aeb6-42a98a2e9e10_20170622_064255_270.jpg, 00:00:18,
4.19m
Debris silt, 15% cross-sectional area loss, Finish



LINE AX_faa065e7-765e-4826-98de-115a3067a3d6_20170622_064632_571.jpg, 00:01:49,
12.73m
Obstruction from 12 o'clock to 12 o'clock, 95% height loss


Inspection Report

Section Number : 4	Date : 22/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : SWMH10X
Operator : RH	Vehicle :	Camera :	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SWMH11a < SWMH10	US MH: SWMH10
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 8.50	DS MH: SWMH11a
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:


1:72	Position m	Code	Observation	MPEG	Photo	Grade			
Depth: SWMH11a									
	0.00	WL	Water level, 5% of sewer height	00:00:00		0			
	0.00	ST	Start of survey	00:02:10		0			
	0.00	MH	Manhole: SWMH11a	00:02:10		0			
	7.87	LC	Sewer lining changes/starts/finishes at this point: start of repair patch	00:00:24		0			
	8.29	LC	Sewer lining changes/starts/finishes at this point: end of repair patch	00:00:40		0			
SWMH10	8.50	FH	Finish survey	00:01:05		0			
Depth:									
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 22/06/2017 - SWMH10X

Section Number : 4	Survey Direction : SWMH11a ↑ SWMH10	PLR : SWMH10X	Client's Ref :	Contractor's Ref :
------------------------------	---	-------------------------	----------------	--------------------



SWMH10X_9aac5131-bd9b-41d0-89fb-81cbdd461637_20170622_065351_994.jpg, 00:00:24,
7.87m
Sewer lining changes/starts/finishes at this point



SWMH10X_19661fd1-2b1b-4a3b-b90b-60378e9481a6_20170622_065335_414.jpg, 00:00:40,
8.29m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 5	Date : 22/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : FWMH4X
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: FWMH4 ® FWMH6	US MH: FWMH4
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length: 18.54	DS MH: FWMH6
Surface Cover:	Pipe Length:	DS Depth:

Use: Foul	Pipe Shape: Circular
Year Laid:	Width / Height: 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:


1:157	Position m	Code	Observation	MPEG	Photo	Grade
Depth: FWMH4 <						

Section Pictures - 22/06/2017 - FWMH4X

Section Number : 5	Survey Direction : FWMH4 ↓ FWMH6	PLR : FWMH4X	Client's Ref :	Contractor's Ref :
------------------------------	--	------------------------	----------------	--------------------



FWMH4X_a5a4e1c0-3f41-46b2-a799-ba14cea9645c_20170622_124154_329.jpg, 00:00:13,
3.92m
Sewer lining changes/starts/finishes at this point



FWMH4X_7d238d10-2c31-4056-ba13-b0f854e45c75_20170622_124209_132.jpg, 00:00:28,
4.67m
Sewer lining changes/starts/finishes at this point

Section Pictures - 22/06/2017 - FWMH4X

Section Number : 5	Survey Direction : FWMH4 ↓ FWMH6	PLR : FWMH4X	Client's Ref :	Contractor's Ref :
------------------------------	--	------------------------	----------------	--------------------



FWMH4X_be5f6ca3-4b84-40f6-a85a-a5fcacce18b9_20170622_124309_459.jpg, 00:01:39,
10.75m
Sewer lining changes/starts/finishes at this point



FWMH4X_cf664817-d747-42e8-b4b5-289354077130_20170622_124352_568.jpg, 00:02:01,
11.44m
Sewer lining changes/starts/finishes at this point

Section Pictures - 22/06/2017 - FWMH4X

Section Number : 5	Survey Direction : FWMH4 ↓ FWMH6	PLR : FWMH4X	Client's Ref :	Contractor's Ref :
------------------------------	--	------------------------	----------------	--------------------



FWMH4X_bd581432-5b32-4c72-bc3b-257f68d926cf_20170622_124544_465.jpg, 00:02:20,
12.44m
Sewer lining changes/starts/finishes at this point



FWMH4X_3f5d34cd-43b8-46bf-a341-98fa62b75929_20170622_124511_205.jpg, 00:02:44,
13.94m
Sewer lining changes/starts/finishes at this point

Section Pictures - 22/06/2017 - FWMH4X

Section Number : 5	Survey Direction : FWMH4 ↓ FWMH6	PLR : FWMH4X	Client's Ref :	Contractor's Ref :
------------------------------	--	------------------------	----------------	--------------------



FWMH4X_88a9eda9-8477-4c78-97fb-2801c5b99fe4_20170622_124623_852.jpg, 00:03:43,
14.52m
Sewer lining changes/starts/finishes at this point



FWMH4X_5235b1f3-41d3-47b2-aef3-8563609d1de4_20170622_124708_162.jpg, 00:03:58,
14.92m
Sewer lining changes/starts/finishes at this point

Section Pictures - 22/06/2017 - FWMH4X

Section Number : 5	Survey Direction : FWMH4 ↓ FWMH6	PLR : FWMH4X	Client's Ref :	Contractor's Ref :
------------------------------	--	------------------------	----------------	--------------------



FWMH4X_c92f4f40-966b-4dac-bea2-30dd2616dc94_20170622_124837_089.jpg, 00:05:10, 17.13m
Sewer lining changes/starts/finishes at this point



FWMH4X_ed670d45-7678-48c9-b225-86665e92ac73_20170622_125005_943.jpg, 00:05:32, 17.95m
Sewer lining changes/starts/finishes at this point


Inspection Report

Section Number : 6	Date : 22/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : LINE AX
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SW04 < LINE A	US MH: LINE A
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length: 2.00	DS MH: SW04
Surface Cover:	Pipe Length:	DS Depth:

Use: Foul	Pipe Shape: Circular
Year Laid:	Width / Height: 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:50	Position m	Code	Observation	MPEG	Photo	Grade
Depth: SW04  LINE A Depth:	0.00	ST	Start of survey	00:00:00		0
	0.00	MH	Manhole: SW04	00:00:00		0
	0.00	WL	Water level, 5% of sewer height	00:00:00		0
	0.01	LC	Sewer lining changes/starts/finishes at this point: start of repair patch	00:00:00		0
	1.14	LC	Sewer lining changes/starts/finishes at this point: end of repair patch	00:00:55		0
	2.00	FH	Finish survey	00:01:00		0
STR no def STR peak STR mean STR total STR grade SER no def SER peak SER mean SER total SER grade 0 0.0 0.0 0.0 1.0 0 0.0 0.0 0.0 1.0						

Section Pictures - 22/06/2017 - LINE AX

Section Number : 6	Survey Direction : SW04 ↑ LINE A	PLR : LINE AX	Client's Ref :	Contractor's Ref :
------------------------------	--	-------------------------	----------------	--------------------



LINE AX_10d967aa-013c-411f-940f-b1f16ea068d3_20170622_155832_243.jpg, 00:00:00,
0.01m
Sewer lining changes/starts/finishes at this point



LINE AX_977b7323-0c73-4586-91dc-48bb27dec19d_20170622_160013_701.jpg, 00:00:55,
1.14m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 7	Date : 22/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : SWMH7X
Operator : RH	Vehicle : NL63 HYS	Camera : Crawler	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SWMH8 < SWMH7	US MH: SWMH7
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 6.50	DS MH: SWMH8
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:55	Position m	Code	Observation	MPEG	Photo	Grade
Depth: SWMH8 0.00 0.00 0.00 4.87 5.67 6.50 SWMH7 Depth:						
	0.00	ST	Start of survey	00:00:00		0
	0.00	MH	Manhole: SWMH8	00:00:00		0
	0.00	WL	Water level, 5% of sewer height	00:00:00		0
	4.87	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:00:38		0
	5.67	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:01:04		0
	6.50	FH	Finish survey	00:01:14		0
STR no defSTR peakSTR meanSTR totalSTR gradeSER no defSER peakSER meanSER totalSER grade 00.00.000.01.000.00.00.01.0						

Section Pictures - 22/06/2017 - SWMH7X

Section Number : 7	Survey Direction : SWMH8 ↑ SWMH7	PLR : SWMH7X	Client's Ref :	Contractor's Ref :
-----------------------	-------------------------------------	-----------------	----------------	--------------------



SWMH7X_403ed8c3-5bb3-4782-8120-80dc687a1669_20170622_174835_108.jpg, 00:00:38,
4.87m
Sewer lining changes/starts/finishes at this point



SWMH7X_051899fe-31e4-47c8-bb6f-31994bfe1854_20170622_174924_754.jpg, 00:01:04,
5.67m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - ESW15X

Section Number : 8	Survey Direction : ESW15 ↓ ESW14	PLR : ESW15X	Client's Ref :	Contractor's Ref :
------------------------------	--	------------------------	----------------	--------------------



ESW15X_3ec77f19-61bf-4152-aa76-f4e0fd1c5cb7_20170623_055005_159.jpg, 00:00:00,
0.60m
Sewer lining changes/starts/finishes at this point




ESW15X_6fe1855c-35e8-4c99-b2ea-e23cb511dbcc_20170623_055102_253.jpg, 00:00:36,
0.97m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - ESW1X

Section Number : 9	Survey Direction : ESW2 ↑ ESW1	PLR : ESW1X	Client's Ref :	Contractor's Ref :
------------------------------	--	-----------------------	----------------	--------------------



ESW1X_4b29e6cd-490b-47bc-83e7-2f95f5e0d252_20170623_060337_733.jpg, 00:00:22,
3.24m
Sewer lining changes/starts/finishes at this point



ESW1X_700d08c7-09af-4d30-8327-ce8141aca2d9_20170623_060428_381.jpg, 00:00:37,
3.59m
Sewer lining changes/starts/finishes at this point


Inspection Report

Section Number : 10	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : EDMH9X
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SC12 < EDMH9	US MH: EDMH9
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length: 2.00	DS MH: SC12
Surface Cover:	Pipe Length:	DS Depth:


Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height: 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:50	Position m	Code	Observation	MPEG	Photo	Grade
						
	0.00	ST	Start of survey			0
	0.00	MH	Manhole: SC12			0
	0.00	WL	Water level, 5% of sewer height	00:00:00		0
	1.11	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:00:14		0
	1.92	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:00:35		0
	2.00	FH	Finish survey	00:00:42		0
STR no def STR peak STR mean STR total STR grade SER no def SER peak SER mean SER total SER grade 0 0.0 0.0 0.0 1.0 0 0.0 0.0 0.0 1.0						

Section Pictures - 23/06/2017 - EDMH9X

Section Number : 10	Survey Direction : SC12 ↑ EDMH9	PLR : EDMH9X	Client's Ref :	Contractor's Ref :
-------------------------------	---	------------------------	----------------	--------------------



EDMH9X_1028eca3-c83e-4294-9535-3f5dc0afc082_20170623_115430_503.jpg, 00:00:14,
1.11m
Sewer lining changes/starts/finishes at this point



EDMH9X_1c9921d1-9b57-4d02-b12d-2d46032187ea_20170623_115512_696.jpg, 00:00:35,
1.92m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 11	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : EDMH10X
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: EDMH11 < EDMH10	US MH: EDMH10
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length: 6.00	DS MH: EDMH11
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height: 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:51	Position m	Code	Observation	MPEG	Photo	Grade
Depth: EDMH11 <						

Section Pictures - 23/06/2017 - EDMH10X

Section Number : 11	Survey Direction : EDMH11 ↑ EDMH10	PLR : EDMH10X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



EDMH10X_b9de2752-edb1-4100-80fb-94f571934139_20170623_122606_461.jpg, 00:00:04,
0.00m
Sewer lining changes/starts/finishes at this point



EDMH10X_184e0cd9-7154-424c-9ab7-e700b0c67050_20170623_122308_167.jpg, 00:00:25,
0.73m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - EDMH10X

Section Number : 11	Survey Direction : EDMH11 ↑ EDMH10	PLR : EDMH10X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



EDMH10X_10becd6d-ca3b-47f4-b675-749b49a00ead_20170623_122402_761.jpg, 00:00:58,
3.51m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 12	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : LINE YX
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SWMH14 < LINE Y	US MH: LINE Y
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 1.00	DS MH: SWMH14
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:50	Position m	Code	Observation	MPEG	Photo	Grade
	0.00	ST	Start of survey	00:00:00		0
	0.00	MH	Manhole: SWMH14	00:00:00		0
	0.00	WL	Water level, 5% of sewer height	00:00:00		0
	0.00	LC	Sewer lining changes/starts/finishes at this point: start of repair patch	00:00:02		0
	0.33	LC	Sewer lining changes/starts/finishes at this point: end of repair patch	00:00:24		0
	1.00	FH	Finish survey	00:00:32		0
STR no def STR peak STR mean STR total STR grade SER no def SER peak SER mean SER total SER grade 0 0.0 0.0 0.0 1.0 0 0.0 0.0 0.0 1.0						

Section Pictures - 23/06/2017 - LINE YX

Section Number : 12	Survey Direction : SWMH14 ↑ LINE Y	PLR : LINE YX	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



LINE YX_021c3de1-5d3d-41df-b5ab-a3a3a360c7d1_20170623_133006_960.jpg, 00:00:02,
0.00m
Sewer lining changes/starts/finishes at this point



LINE YX_0e3e7a11-6a3b-4479-8b92-bf6e4fb0f9d8_20170623_133045_762.jpg, 00:00:24,
0.33m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 13	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : LINE BX
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: FWMH3 < LINE B	US MH: LINE B
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length: 1.00	DS MH: FWMH3
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height: 100 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:50	Position m	Code	Observation	MPEG	Photo	Grade
	0.00	ST	Start of survey	00:01:37		0
	0.00	MH	Manhole: FWMH3	00:01:37		0
	0.00	WL	Water level, 5% of sewer height	00:01:37		0
	0.01	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:00:00		0
	0.35	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:00:44		0
	1.00	FH	Finish survey	00:00:49		0
STR no def STR peak STR mean STR total STR grade SER no def SER peak SER mean SER total SER grade 0 0.0 0.0 0.0 1.0 0 0.0 0.0 0.0 1.0						

Section Pictures - 23/06/2017 - LINE BX

Section Number : 13	Survey Direction : FWMH3 ↑ LINE B	PLR : LINE BX	Client's Ref :	Contractor's Ref :
-------------------------------	---	-------------------------	----------------	--------------------



LINE BX_98fe3b8d-390e-491a-974a-eccb7cfcdb41_20170623_134034_080.jpg, 00:00:00, 0.01m
Sewer lining changes/starts/finishes at this point



LINE BX_f2997f23-f1f9-4459-bfec-56504196a0b0_20170623_134129_319.jpg, 00:00:44, 0.35m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 14	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : LINE AX
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: EFW03 < LINE A	US MH: LINE A
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length: 30.00	DS MH: EFW03
Surface Cover:	Pipe Length:	DS Depth:

Use: Trade effluent	Pipe Shape: Circular
Year Laid:	Width / Height: 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Cast iron

Comment:
Recommendation:

1:254	Position m	Code	Observation	MPEG	Photo	Grade
Depth: EFW03 </						

Section Pictures - 23/06/2017 - LINE AX

Section Number : 14	Survey Direction : EFW03 ↑ LINE A	PLR : LINE AX	Client's Ref :	Contractor's Ref :
-------------------------------	---	-------------------------	----------------	--------------------



LINE AX_d3bffbfc-e241-4174-9c5a-c0807aeeb59f_20170623_145635_959.jpg, 00:00:25, 5.02m
General observation



LINE AX_53e7044a-faef-460c-9acc-e4cde0e60f57_20170623_145847_261.jpg, 00:01:53, 27.71m
General observation


Inspection Report

Section Number : 15	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : MH4X
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: MH4 ® MH3	US MH: MH4
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 25.00	DS MH: MH3
Surface Cover:	Pipe Length:	DS Depth:

Use: Trade effluent	Pipe Shape: Circular
Year Laid:	Width / Height 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Cast iron

Comment:
Recommendation:

1:211	Position m	Code	Observation	MPEG	Photo	Grade
Depth: MH4  0.00 0.00 0.00 0.00 8.57 16.98 25.00 Depth: MH3						
	0.00	ST	Start of survey	00:02:15		0
	0.00	MH	Manhole: MH4	00:02:15		0
	0.00	WL	Water level, 5% of sewer height	00:02:15		0
	0.00	GO	General observation: clean line	00:00:00		0
	8.57	GO	General observation: clean line	00:00:20		0
	16.98	GO	General observation: clean line	00:01:04		0
	25.00	FH	Finish survey	00:01:49		0
STR no def 0						
STR peak 0.0						
STR mean 0.0						
STR total 0.0						
STR grade 1.0						
SER no def 0						
SER peak 0.0						
SER mean 0.0						
SER total 0.0						
SER grade 1.0						

Section Pictures - 23/06/2017 - MH4X

Section Number : 15	Survey Direction : MH4 ↓ MH3	PLR : MH4X	Client's Ref :	Contractor's Ref :
-------------------------------	--	----------------------	----------------	--------------------



MH4X_4fb7f44a-4363-4648-a26a-c8f01d422142_20170623_150213_686.jpg, 00:00:20, 8.57m
General observation



MH4X_769206cb-55be-4d24-87d2-f92dce9deaf2_20170623_150315_109.jpg, 00:01:04, 16.98m
General observation

Inspection Report

Section Number : 16	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : ESW6X
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: ESW6 ® ESW7	US MH: ESW6
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 7.00	DS MH: ESW7
Surface Cover:	Pipe Length:	DS Depth:


Use: Foul	Pipe Shape: Circular
Year Laid:	Width / Height 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:60	Position m	Code	Observation	MPEG	Photo	Grade
Depth: ESW6 <						

Section Pictures - 23/06/2017 - ESW6X

Section Number : 16	Survey Direction : ESW6 ↓ ESW7	PLR : ESW6X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-----------------------	----------------	--------------------



ESW6X_137b160a-0fda-49b2-8dfa-3f02a1eb49f4_20170623_152309_067.jpg, 00:00:24, 5.06m
Sewer lining changes/starts/finishes at this point



ESW6X_48006c78-d775-4be3-81e2-b1af41b6605d_20170623_152353_093.jpg, 00:00:47,
6.22m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 17	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : SWMH14X
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SWMH13 < SWMH14	US MH: SWMH14
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 30.00	DS MH: SWMH13
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:254	Position m	Code	Observation	MPEG	Photo	Grade																																																												
Depth: SWMH13 Depth: SWMH14 <table><tr><td>0.00</td><td>ST</td><td>Start of survey</td><td>00:00:53</td><td>0</td></tr><tr><td>0.00</td><td>MH</td><td>Manhole: SWMH13</td><td>00:00:53</td><td>0</td></tr><tr><td>0.00</td><td>WL</td><td>Water level, 5% of sewer height</td><td>00:00:00</td><td>0</td></tr><tr><td>4.35</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: start of repair patch</td><td>00:00:33</td><td>0</td></tr><tr><td>5.22</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: end of patch repair</td><td>00:01:51</td><td>0</td></tr><tr><td>5.94</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: start of patch repair</td><td>00:02:19</td><td>0</td></tr><tr><td>6.87</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: end of patch repair</td><td>00:02:38</td><td>0</td></tr><tr><td>7.62</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: start of patch repair</td><td>00:02:55</td><td>0</td></tr><tr><td>8.49</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: end of patch repair</td><td>00:03:20</td><td>0</td></tr><tr><td>26.17</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: start of patch repair</td><td>00:04:59</td><td>0</td></tr><tr><td>27.98</td><td>LC</td><td>Sewer lining changes/starts/finishes at this point: end of patch repair</td><td>00:05:21</td><td>0</td></tr><tr><td>30.00</td><td>FH</td><td>Finish survey</td><td>00:05:30</td><td>0</td></tr></table>							0.00	ST	Start of survey	00:00:53	0	0.00	MH	Manhole: SWMH13	00:00:53	0	0.00	WL	Water level, 5% of sewer height	00:00:00	0	4.35	LC	Sewer lining changes/starts/finishes at this point: start of repair patch	00:00:33	0	5.22	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:01:51	0	5.94	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:02:19	0	6.87	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:02:38	0	7.62	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:02:55	0	8.49	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:03:20	0	26.17	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:04:59	0	27.98	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:05:21	0	30.00	FH	Finish survey	00:05:30	0
0.00	ST	Start of survey	00:00:53	0																																																														
0.00	MH	Manhole: SWMH13	00:00:53	0																																																														
0.00	WL	Water level, 5% of sewer height	00:00:00	0																																																														
4.35	LC	Sewer lining changes/starts/finishes at this point: start of repair patch	00:00:33	0																																																														
5.22	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:01:51	0																																																														
5.94	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:02:19	0																																																														
6.87	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:02:38	0																																																														
7.62	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:02:55	0																																																														
8.49	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:03:20	0																																																														
26.17	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:04:59	0																																																														
27.98	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:05:21	0																																																														
30.00	FH	Finish survey	00:05:30	0																																																														
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade																																																									
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0																																																									

Section Pictures - 23/06/2017 - SWMH14X

Section Number : 17	Survey Direction : SWMH13 ↑ SWMH14	PLR : SWMH14X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



SWMH14X_5ee8f9ab-a427-48ce-83c6-79fee2651629_20170623_153055_237.jpg, 00:00:33,
4.35m
Sewer lining changes/starts/finishes at this point



SWMH14X_3cf4f22c-c7c9-4d10-aa1f-c9d3c18e2699_20170623_153243_031.jpg, 00:01:51,
5.22m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - SWMH14X

Section Number : 17	Survey Direction : SWMH13 ↑ SWMH14	PLR : SWMH14X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------




SWMH14X_e0851588-5522-4343-9d17-d992fabaab4a_20170623_153331_869.jpg, 00:02:19,
5.94m
Sewer lining changes/starts/finishes at this point



SWMH14X_bc4eaccb-041a-4fe0-ace0-eca2422328ec_20170623_153408_637.jpg, 00:02:38,
6.87m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - SWMH14X

Section Number : 17	Survey Direction : SWMH13 ↑ SWMH14	PLR : SWMH14X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



SWMH14X_039edf5b-f555-4637-8925-239dbac8b440_20170623_153441_115.jpg, 00:02:55,
7.62m
Sewer lining changes/starts/finishes at this point



SWMH14X_491e6763-f1d0-4a81-825a-773ee96bd826_20170623_153750_342.jpg, 00:04:59,
26.17m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - SWMH14X

Section Number : 17	Survey Direction : SWMH13 ↑ SWMH14	PLR : SWMH14X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



SWMH14X_58a39c6a-91ba-4d30-a303-18e4979c10cb_20170623_153836_690.jpg, 00:05:21,
27.98m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 18	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : SWMH13X
Operator : RH	Vehicle : NL63 HYS	Camera : Pushrod	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SWMH13 ® SWMH12	US MH: SWMH13
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 13.60	DS MH: SWMH12
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height 150 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:115	Position m	Code	Observation	MPEG	Photo	Grade
Depth: SWMH13 <						

Section Pictures - 23/06/2017 - SWMH13X

Section Number : 18	Survey Direction : SWMH13 ↓ SWMH12	PLR : SWMH13X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



SWMH13X_8cb6fbfa-99dc-4d21-a428-313d3db1b8f1_20170623_154227_380.jpg, 00:06:32,
3.98m
Sewer lining changes/starts/finishes at this point



SWMH13X_5f5bbc2f-0c8b-4f0e-badc-9bf328a41d29_20170623_154327_385.jpg, 00:00:16,
5.13m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - SWMH13X

Section Number : 18	Survey Direction : SWMH13 ↓ SWMH12	PLR : SWMH13X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



SWMH13X_bd16db54-2aa8-43dd-975d-c54e5d65a4a8_20170623_154422_191.jpg, 00:00:49,
7.73m
Sewer lining changes/starts/finishes at this point



SWMH13X_4f7a62b8-330c-4daf-a230-443930e307f4_20170623_154503_096.jpg, 00:01:02,
8.53m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - SWMH13X

Section Number : 18	Survey Direction : SWMH13 ↓ SWMH12	PLR : SWMH13X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



SWMH13X_bacebbe2-a1fc-441e-b5a9-b96c6fbb4217_20170623_154609_181.jpg, 00:01:34,
12.95m
Sewer lining changes/starts/finishes at this point



SWMH13X_08acc3c8-6cf6-41b0-aeae-9900846d65c2_20170623_154717_579.jpg, 00:01:51,
13.60m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 19	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : SWMH12X
Operator : RH	Vehicle :	Camera :	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: SWMH12 ® SWMH13	US MH: SWMH12
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 12.68	DS MH: SWMH13
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height 150 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:108	Position m	Code	Observation	MPEG	Photo	Grade																																																							
Depth: SWMH12 0.00 0.00 0.00 5.49 5.90 10.54 11.37 12.52 12.63 12.68 12.68 Depth: SWMH13 <table><tr><td>ST</td><td>Start of survey</td><td>00:02:33</td><td></td><td>0</td></tr><tr><td>MH</td><td>Manhole: SWMH12</td><td>00:02:33</td><td></td><td>0</td></tr><tr><td>WL</td><td>Water level, 5% of sewer height</td><td>00:02:33</td><td></td><td>0</td></tr><tr><td>LC</td><td>Sewer lining changes/starts/finishes at this point: start of patch repair</td><td>00:02:33</td><td></td><td>0</td></tr><tr><td>LC</td><td>Sewer lining changes/starts/finishes at this point: end of patch repair</td><td>00:00:00</td><td></td><td>0</td></tr><tr><td>LC</td><td>Sewer lining changes/starts/finishes at this point: start of patch repair</td><td>00:00:19</td><td></td><td>0</td></tr><tr><td>LC</td><td>Sewer lining changes/starts/finishes at this point: end of patch repair</td><td>00:00:44</td><td></td><td>0</td></tr><tr><td>LC</td><td>Sewer lining changes/starts/finishes at this point: start of patch repair</td><td>00:01:30</td><td></td><td>0</td></tr><tr><td>LC</td><td>Sewer lining changes/starts/finishes at this point: end of patch repair</td><td>00:01:48</td><td></td><td>0</td></tr><tr><td>DC</td><td>Dimension of sewer changes, new (vertical) diameter: 100mm</td><td>00:02:01</td><td></td><td>0</td></tr><tr><td>FH</td><td>Finish survey</td><td>00:02:11</td><td></td><td>0</td></tr></table>							ST	Start of survey	00:02:33		0	MH	Manhole: SWMH12	00:02:33		0	WL	Water level, 5% of sewer height	00:02:33		0	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:02:33		0	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:00:00		0	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:00:19		0	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:00:44		0	LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:01:30		0	LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:01:48		0	DC	Dimension of sewer changes, new (vertical) diameter: 100mm	00:02:01		0	FH	Finish survey	00:02:11		0
ST	Start of survey	00:02:33		0																																																									
MH	Manhole: SWMH12	00:02:33		0																																																									
WL	Water level, 5% of sewer height	00:02:33		0																																																									
LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:02:33		0																																																									
LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:00:00		0																																																									
LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:00:19		0																																																									
LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:00:44		0																																																									
LC	Sewer lining changes/starts/finishes at this point: start of patch repair	00:01:30		0																																																									
LC	Sewer lining changes/starts/finishes at this point: end of patch repair	00:01:48		0																																																									
DC	Dimension of sewer changes, new (vertical) diameter: 100mm	00:02:01		0																																																									
FH	Finish survey	00:02:11		0																																																									
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade																																																				
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0																																																				

Section Pictures - 23/06/2017 - SWMH12X

Section Number : 19	Survey Direction : SWMH12 ↓ SWMH13	PLR : SWMH12X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



SWMH12X_f37b4eed-09d8-4083-824e-31aa07f8e42c_20170623_155844_389.jpg, 00:02:33,
5.49m
Sewer lining changes/starts/finishes at this point



SWMH12X_81ab399a-8ae1-4155-81d9-0ddff52074c4_20170623_155928_081.jpg, 00:00:00,
5.90m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - SWMH12X

Section Number : 19	Survey Direction : SWMH12 ↓ SWMH13	PLR : SWMH12X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



SWMH12X_aec8aa87-c7b4-47b6-9bc8-d217bd1f5245_20170623_160021_820.jpg, 00:00:19,
10.54m
Sewer lining changes/starts/finishes at this point



SWMH12X_075f19c8-260a-4442-bee9-583696bc34d0_20170623_160120_183.jpg, 00:00:44,
11.37m
Sewer lining changes/starts/finishes at this point

Section Pictures - 23/06/2017 - SWMH12X

Section Number : 19	Survey Direction : SWMH12 ↓ SWMH13	PLR : SWMH12X	Client's Ref :	Contractor's Ref :
-------------------------------	--	-------------------------	----------------	--------------------



SWMH12X_d05aedic9-15cb-41da-85b7-c522af7caab4_20170623_160227_720.jpg, 00:01:30,
12.52m
Sewer lining changes/starts/finishes at this point



SWMH12X_c8d34e41-a42c-494e-8bee-21741b3b94a9_20170623_160421_393.jpg, 00:02:01,
12.68m
Dimension of sewer changes, new (vertical) diameter: 100mm

Inspection Report

Section Number : 20	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : MH1X
Operator : RH	Vehicle :	Camera :	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction:	US MH: MH1
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 1.00	DS MH: MH2
Surface Cover:	Pipe Length:	DS Depth:

Use: Surface water	Pipe Shape: Circular
Year Laid:	Width / Height 150 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:50	Position m	Code	Observation	MPEG	Photo	Grade
Depth: MH1						

Section Pictures - 23/06/2017 - MH1X

Section Number : 20	Survey Direction :	PLR : MH1X	Client's Ref :	Contractor's Ref :
-------------------------------	--------------------	----------------------	----------------	--------------------



MH1X_1d1fd957-b692-47b7-a99a-d8147e191c6d_20170623_160803_390.jpg, 00:02:11, 0.25m
Sewer lining changes/starts/finishes at this point

Inspection Report

Section Number : 21	Date : 23/06/2017	Client's Ref :	Weather : Dry	Critical Drain/Sewer:	PLR : FWMH6X
Operator : RH	Vehicle :	Camera :	Preset :	Cleaned : no	Type of Drain :

Place: 2 Sisters	Direction: FWMH6 ® FWMH6a	US MH: FWMH6
Road: Industrial Estate Road	Catchment: Llangefni LL77 7UX	US Depth:
Location:	Total Length 16.00	DS MH: FWMH6a
Surface Cover:	Pipe Length:	DS Depth:

Use: Foul	Pipe Shape: Circular
Year Laid:	Width / Height 225 / 0
Purpose: Post inspection of repairs or renovations	Flow Control:
Lining:	Pipe Material: Vitrified clay

Comment:
Recommendation:

1:136	Position m	Code	Observation	MPEG	Photo	Grade			
Depth: FWMH6 0.00 ST Start of survey 00:02:11 0 0.00 MH Manhole: FWMH6 00:02:11 0 0.00 WL Water level, 5% of sewer height 00:02:11 0 14.86 LC Sewer lining changes/starts/finishes at this point: start of patch repair 00:02:11 0 15.48 LC Sewer lining changes/starts/finishes at this point: end of patch repair 00:02:11 0 16.00 FH Finish survey 00:02:11 0 Depth:									
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 23/06/2017 - FWMH6X

Section Number : 21	Survey Direction : FWMH6 ↓ FWMH6a	PLR : FWMH6X	Client's Ref :	Contractor's Ref :
-------------------------------	---	------------------------	----------------	--------------------



FWMH6X_dfcc0f2a-afa2-4db1-bc94-2e6f148f5554_20170623_161706_052.jpg, 00:02:11,
14.86m
Sewer lining changes/starts/finishes at this point



FWMH6X_daff379e-f0fc-4b2e-9292-191b6c348b9d_20170623_161818_438.jpg, 00:02:11,
15.48m
Sewer lining changes/starts/finishes at this point