

June 2022

Day	Downtime	Availability	Rationale
1	0	100.00%	
2	0	100.00%	
3	1.5	93.75%	Boiler PLC CPU froze, reset and restarted boiler
4	2	91.67%	Sudden swing in Boiler O2 caused turbine trip caused by loss of air seal in West Ash conveyor during sootblowing, recovered boiler and restarted Turbine
5	0	100.00%	
6	0	100.00%	
7	0	100.00%	
8	0	100.00%	
9	0	100.00%	
10	0	100.00%	
11	0	100.00%	
12	0	100.00%	
13	0	100.00%	
14	0	100.00%	
15	0	100.00%	
16	0	100.00%	
17	0	100.00%	
18	0	100.00%	
19	0	100.00%	
20	0	100.00%	
21	0	100.00%	
22	0	100.00%	
23	0	100.00%	
24	0	100.00%	
25	0	100.00%	
26	0	100.00%	
27	0	100.00%	
28	0	100.00%	
29	0	100.00%	
30	0	100.00%	
Month	3.5	99.51%	