

6 APR 2018

Schedule 1 - Notification of abnormal emissions

This page outlines the information that the Operator must provide to satisfy conditions 5.1.1 and 5.1.2 of this Permit.

Units of measurement used in information supplied under Part A and B requirements shall be appropriate to the circumstances of the emission. Where appropriate, a comparison should be made of actual emissions and authorised emission limits.

If any information is considered commercially confidential, it should be separated from non-confidential information, supplied on a separate sheet and accompanied by an application for commercial confidentiality under the provisions of the PPC Regulations.

Part A

Permit Number	AP3433ES
Name of Operator	2 Sisters Red Meat t/a St Merryn Foods
Location of Installation	Merthyr Tydfil
Location of the emission	Within the catchment for the W1 discharge point
Time and date of the emission	08/02/2018

Substance(s) emitted	Media	Best estimate of the quantity or the rate of emission	Time during which the emission took place
Mineral Oils and Hydrocarbons	Water U1	21.2 mg/l	08/02/2018
Total Suspended Solids	Water U2	58.0 mg/l	08/02/2018

SHOULD
BE MIN
OIL + HYDROCARBONS.

Measures taken, or intended to be taken, to stop the emission	Interceptor audit to be scheduled with a third party to identify any issues and repair if required.
---	---

Part B

Any more accurate information on the matters for notification under Part A.	Emission due to a previously identified fault in the W1 interceptor. This had been repaired in 2017 to allow time for a replacement interceptor to be designed, but this repair may have since failed.
Measures taken, or intended to be taken, to prevent a recurrence of the incident	Interceptor audit to be scheduled with a third party to identify any issues and repair where possible, or to submit options for the interceptor's replacement.
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission	Booms have been in place downstream of the W1 sampling point, at the site boundary. These will have prevented any pollution or harm from this emission.
The dates of any unauthorised emissions from the installation in the preceding 24 months.	23/9/17 - Contractor HGV collision resulting in fuel spill 13/04/17 - W1 Emission of Mineral oil and hydrocarbon 30/03/17 - S1 Emission of Mineral oil and hydrocarbon 02/03/17 - W1 Emission of Mineral oil and hydrocarbon 06/06/16 - Refrigerant leak from crack pipe in system MT3 02/06/16 - W2 Emission hydrocarbon

Name*	Matt Dight
Post	Environmental Manager
Signature	
Date	6/4/2018

Public Register
EP 13/4/18

* authorised to sign on behalf of 2 Sisters Red Meat Ltd

Schedule 1 - Notification of abnormal emissions

This page outlines the information that the Operator must provide to satisfy conditions 5.1.1 and 5.1.2 of this Permit.

Units of measurement used in information supplied under Part A and B requirements shall be appropriate to the circumstances of the emission. Where appropriate, a comparison should be made of actual emissions and authorised emission limits.

If any information is considered commercially confidential, it should be separated from non-confidential information, supplied on a separate sheet and accompanied by an application for commercial confidentiality under the provisions of the PPC Regulations.

Part A

Permit Number	AP3433ES
Name of Operator	2 Sisters Red Meat t/a St Merryn Foods
Location of Installation	Merthyr Tydfil
Location of the emission	Within the catchment for the W1 discharge point
Time and date of the emission	22/02/2018

Substance(s) emitted	Media	Best estimate of the quantity or the rate of emission	Time during which the emission took place
Mineral Oils and Hydrocarbons	Water W1	17.4 mg/l	22/02/2018
Total Suspended Solids	Water W2	68.0.0 mg/l	22/02/2018

Min oil +
hydrocarbons


Measures taken, or intended to be taken, to stop the emission	Interceptor audit to be scheduled with a third party to identify any issues and repair if required.
---	---

Part B

Any more accurate information on the matters for notification under Part A.	Emission due to a previously identified fault in the W1 interceptor. This had been repaired in 2017 to allow time for a replacement interceptor to be designed, but this repair may have since failed.
Measures taken, or intended to be taken, to prevent a recurrence of the incident	Interceptor audit to be scheduled with a third party to identify any issues and repair where possible, or to submit options for the interceptor's replacement.
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission	Booms have been in place downstream of the W1 sampling point, at the site boundary. These will have prevented any pollution or harm from this emission.
The dates of any unauthorised emissions from the installation in the preceding 24 months.	02/02/18 – W1 Emission of Mineral oil and hydrocarbon and suspended solids 23/09/17 – Contractor HGV collision resulting in fuel spill 13/04/17 – W1 Emission of Mineral oil and hydrocarbon 30/03/17 – S1 Emission of Mineral oil and hydrocarbon 02/03/17 – W1 Emission of Mineral oil and hydrocarbon 06/06/16 – Refrigerant leak from crack pipe in system MT3 02/06/16 – W2 Emission hydrocarbon

Name*	Matt Dight
Post	Environmental Manager

Permit and introductory note: the PPC Regulations
Schedule 1 - Notification of abnormal emissions

Signature	
Date	6/4/2018

* authorised to sign on behalf of 2 Sisters Red Meat Ltd