

Photos from inspection on 03.10.19



Inlet, primary tank and sludge tankering point.



Trickling filter bed.



Sanitary waste on filter media.



Outlet pipe from trickling filter bed flows into an open chamber where it can be observed.



Suspected location of soakaway pit and herringbone soakaway