

**Site Photos**

Maerdy Mill, Corwen, LL21 0NR

Photographs taken 01/07/2023

Afon Ceirw as photographed at approx Q95 as indicated by [live flow data](#) from Gauging Station 67023 on tributary further down the Dee catchment

Photos locations are numbered can be identified on the image below.



1a Weir: Upstream of the weir looking downstream towards leat entrance



1b Weir: Downstream of the weir looking back up



1c Weir: Downstream of the weir



2a Leat channel: The channel running down to the sluice gate



2b Leat channel: The channel running down to the sluice gate



2c Leat channel: The channel running down to the sluice gate



2d Leat channel: The channel running down to the sluice gate



3a Tailrace: The discharge point back into the river



3b Tailrace: The discharge point back into the river




3c Tailrace: The discharge point back into the river



3d Tailrace: The discharge point back into the river




3e Tailrace: The discharge point back into the river



4a Depleted reach: The depleted reach from the weir to the tailrace confluence



4b Depleted reach: The depleted reach from the weir to the tailrace confluence



4c Depleted reach: The depleted reach from the weir to the tailrace confluence



4d Depleted reach: The depleted reach from the weir to the tailrace confluence

