


## Schedule 5 – Notification

### Part A

<b>Permit Number</b>	EPR/BP 3635MR
<b>Name of operator</b>	Harsco Environmental
<b>Location of Facility</b>	Harsco Ring Fenced Site Tata Steel Port Talbot
<b>Date reported</b>	13 <sup>th</sup> October 2023

<b>Date and time of incident</b>	25 <sup>th</sup> , 27 <sup>th</sup> 29 <sup>th</sup> & 30 <sup>th</sup> September
<b>Location</b>	Lancing Booth
<b>Substance released</b>	No release of particulates from the stack during the periods of non – compliance.
<b>Measures taken or intended to be taken to stop any emission</b>	Although the particulate monitor is now working within normal parameters, it has been decided to arrange for the monitor to be inspected 3 months earlier than expected
<b>Description of the failure or accident</b>	On 4 occasions there was no recordings of particulate data being sent to the dust monitor, unable to determine the cause of the non-transfer of data and ensuring the monitor is inspected.

<b>Name</b>	Paul Morgan
<b>Post</b>	EHS Manager
<b>Signature</b>	
<b>Date</b>	13/10/23