


Schedule 5 – Notification

Part A

Permit Number	EPR/BP 3635MR
Name of operator	Harsco Environmental
Location of Facility	Harsco Ring Fenced Site Tata Steel Port Talbot
Date reported	13 th October 2023

Date and time of incident	2 nd , 3 rd and 4 th October
Location	Lancing Booth
Substance released	No release of particulates from the stack during the periods of non – compliance.
Measures taken or intended to be taken to stop any emission	Although the particulate monitor is now working within normal parameters, the stack testing was brought forward to the 24 th November. The tests results have shown that the stack monitor was operational within the specified emission limit value of 20mg/m ³ . Also the stack monitoring system was serviced to ensure full compliance, this was carried out on the 16 th November 2023.
Description of the failure or accident	On 3 occasions there was no recordings of particulate data being sent to the dust monitor, unable to determine the cause of the non-transfer of data and ensuring the monitor is inspected.

Name	Paul Morgan
Post	EHS Manager
Signature	
Date	11/01/24