

MWC0183N SITE PHOTOGRAPHS



Timber beam to be replaced



View from the north side of the viaduct



View of access route for machines & personnel



Typical works area underneath structure

