



WASTE MANAGEMENT LICENCED SITE INSPECTION REPORT

LANDFILL DISPOSAL SITE

SITE NAME: TYTHYSTON	OPERATOR: DAVIDS BROS (LWIST) LTD.	KEY
SITE ADDRESS: LANDFILL	DATE: 4/3/97	Satisfactory ✓
LICENCE NO: 11	TIME: 15:00	Not satisfactory x
		Not inspected o

A
Entrance

	KEY	COMMENTS
1. Site Entrance	✓	use road length.
2. Security	✓	
3. Wheel Cleaning	✓	
4. Vehicle reception	✓	
5. Office Facilities	✓	
- Welfare	✓	
- Documentation	✓	
- Staff	✓	

B
Landfill Area

1. Waste Handling	✓	water ponding entrance to working area - soaker bay.
2. Waste Tipping and Working Area	✓	
3. Site Engineering	N/A.	
4. Drainage	✓	
5. Cover Material	✓	
6. Site Roads	✓	
7. Boundary Fence	✓	
8. Gas and Leachate Management	✓	
9. Plant and Equipment	✓	
10. Unpermitted Wastes Storage	✓	
		drum removed from site disposal

C
Environmental
Control

1. Dust, odour, noise	✓	last visit Reithel 6/2/97
2. Pests	✓	
3. Litter	✓	
4. Health and Safety	o	
5. Emergency Equipment	o	

D
General
Comments
and
Action
Required

GENERAL COMMENTS

Working area low and at entrance to working area, minimising travel on site roads.

Muddy at lower end where water collecting soaker bay to be constructed here.

One drum was tipped during inspection - immediately removed for off site disposal.



INTERNAL-1



FORM-2

SPECIFIC LICENCE CONDITIONS BREACHED	
CONDITION NO.	PROPOSED COMPLIANCE DATE

Waste Regulation
Officer:
Operator:

R. Tipping
6/2/97

Samples Taken:
Photographs Taken:
Weather Conditions:

YES/NO
YES/NO