

LANDFILL SITE INSPECTION REPORT

ENVIRONMENTAL PROTECTION ACT 1990

DATE :- 1 JUNE 1994

WEATHER :- DRY/WARM

NAME, ADDRESS AND LICENCE NO. OF SITE	Tythegston 11
NAME OF LICENCE HOLDER	Davies Bros. (Waste) Ltd
CONDITION OF APPROACH AND EXIT ROADS	Satisfactory
LITTER/FLY TIPPING IN SITE ENVIRONS	Minimal
SITE IDENTIFICATION	Satisfactory
SITE OPEN/CLOSED	Open
SECURITY	Satisfactory
MANNING LEVELS/SUPERVISION	Satisfactory
CONDITION OF SITE ROADS	Satisfactory
ON SITE LITTER CONTROL	Satisfactory
WHEEL CLEANSING	Not Required
WEIGHBRIDGE	Not Examined
WASTE RECORDS/SITE LOG	A deposit of "sludge" from 3M was accompanied by a note carrying the wrong description of "General Rubbish". All specific waste streams must be identified as such and consideration given to their suitability, if necessary by chemical analysis.
VERMIN/INSECTS	Records of Pest Control were satisfactory

DUST/ODOUR/NOISE	Minor Levels of Dust and Odour Near Working. Residents in Danygraig area complained of foul smells reaching their properties in early hours of Bank Holiday Weekend - P. Warwick agreed to monitor situation.
FIRES	Nil
WORKING AREA	Small and Well Controlled High Aspect of Site
COVERING MATERIAL	Generally Adequate
UNAUTHORISED WASTE	Not Apparent. A deposit of "sludge" from 3M was accompanied by a note carrying the wrong description of "General Rubbish". All specific waste streams must be identified as such and consideration given to their suitability, if necessary by chemical analysis.
DRAINAGE	Appeared to be Satisfactory. The Operator should take full advantage of the summer months to ensure there will be no production or ponding of foul water during wet weather.
LEVELLING AND COMPACTING	Satisfactory
LANDFILL GAS	Flare was operating satisfactory during time of inspection.

GENERAL REMARKS: In general the site was found to be operating satisfactorily during the inspection.

INSPECTED BY: A. EVANS