

Inspection photographs 12/02/21



CSO outfall flap valve clogged with debris



Sewage type debris in vegetation immediately downstream of CSO outfall



Screen bypass with evidence of 'rag'

Screen

Mechanical helical brush screen cleaner

Weir

Sewer



Screen clearing 'flipper arm'



Sewer penstock



Sewer penstock control vale



Sewer and screen access points. Power unit in background.



Emergency contact details



Asset grounds



Asset from outfall into River Rhymney. Chain link fence visible.