

Arla, Llaandyrnog

Final site inspection 16.04.2021

Photo 1 & 2 – top yard and bulk tank area now empty. Green firewater tank remains.



Photo 2 – two general waste skips remain as part of final site tidy-up



Arla, Llaandyrnog

Final site inspection 16.04.2021

Photo 3 – Cold store area, all refrigeration equipment removed



Photo 4 – old DERV tank, empty and cleaned.



Arla, Llaandyrnog

Final site inspection 16.04.2021

Photo 5 & 6- Final two silos removed, awaiting transport off site



Arla, Llaandyrnog
Final site inspection 16.04.2021
Photo 7 – ETP and bulk chemical tanks access road



Photo 8 – grassed area behind ETP bund wall



Arla, Llaandyrnog
Final site inspection 16.04.2021
Photo 9 – ETP bund and adjacent grassland



Photo 10 – ETP control cabin, control units removed



Arla, Llaandyrnog
Final site inspection 16.04.2021
Photo 11 – concrete base below chemical tanks area



Photo 12 – grassed area outside ETP chemical tank



Arla, Llaandyrnog

Final site inspection 16.04.2021

Photo 13 – damaged flooring in the indoor checmicals storage area, further detail supplied following visit.




Photo 14 – tanks and ancillary pipework removed adjacent to site entryway



Arla, Llaandyrnog
Final site inspection 16.04.2021
Photo 15 – scrap metal skip from site clearance



Photo 16 – Borehole meter – Point A, Abstraction Licence 24/66/1/0047



Arla, Llaandyrnog

Final site inspection 16.04.2021

Photo 17 – Borehole meter – Point B, Abstraction Licence 24/66/1/0047




Photo 18 – Site entryway and bund with tanks removed. Penstock manhole.



Arla, Llaandyrnog
Final site inspection 16.04.2021
Photo 19 – Calor Gas tank remaining



Photo 20 – Milk intake area, silos removed



Arla, Llaandyrnog

Final site inspection 16.04.2021

Photo 21 – Dosing chemicals bund adjacent to boiler house, ancillary pipework removed. Bund tray in foreground is empty



Photo 22 – Dosing chemicals bund – detached pipework breaches the wall on the left side



Arla, Llaandyrnog

Final site inspection 16.04.2021

Photo 23 – Dosing chemicals bund, two empty containers remain. Photos following removal after the visit supplied



Arla, Llaandyrnog
Final site inspection 16.04.2021
Photos 24 &25 – duty and standby boilers



Arla, Llaandyrnog

Final site inspection 16.04.2021

Photo 26 – small container storage, few very small capacity (<2.5l) nominally empty containers remained and would be removed during the clearance. Water staining from the fire hydrant pipe to the right.




Photo 27 – trash screen at the upstream end of the Nant Simon culvert was clear.



Arla, Llaandyrnog
Final site inspection 16.04.2021
Photo 28 – internal plant and equipment removed



Photo 29 – empty chemical tanks inside factory. Evidence of contractor cleaning sent with surrender application.



Arla, Llaandyrnog

Final site inspection 16.04.2021

Photos 30 & 31 – final manhole collecting site surface drainage and culverted Nant Simon in site entryway. Running water is clear and no evidence of fungus or discolouration in the chamber.

