



Photo 1: Primary Settlement Chamber (below grass) – Liquids pumped over to 2<sup>nd</sup> chamber (below grass) – Liquids pumped to Secondary Treatment System via over ground pipe network



Photo 2: Secondary Treatment System (with 7 covers on)



Photo 3: Trickling filters closest to inlet in Secondary Treatment System (covers removed)



Photo 4: Trickling filters closest to outlet (in red) leading to discharge point in Secondary Treatment System (covers removed)



Location of outlet from secondary treatment system

Photo 5: Suspected discharge environment (reen). Discharge point somewhere in red box.



Photo 6: Reen connected to discharge reen. Reen smelt of sewage.



Map 1: Showing locations of photos