

Photograph 1 – Photograph taken in the middle of the hardstanding area facing north towards environmental compound



Photograph 2 – Photograph of the vehicle garages taken in the middle of the hardstanding area facing south



Photograph 3 – Photograph of the leachate storage tanks taken from the middle of the hardstanding looking west



Photograph 4 - Photograph of the vehicle wheel wash taken from the middle of the hardstanding looking north west



Photograph 5 - Photograph taken from the middle of the hardstanding facing east towards



Photograph 6 - Photograph taken of the water saturated organic rich horizon identified at 4.60m within BH5



Photograph 7 – Photograph taken from the middle of the hardstanding facing north across the colliery spoil heap



Photograph 8 – Photograph of the environmental compound taken from the northern edge of the colliery spoil heap facing north



Photograph 9 – Photograph taken on the access road north of the environmental compound facing south



Photograph 10 – Photograph taken from the western edge of the colliery spoil heap facing south east towards the hardstanding



Photograph 11 – Photograph of the on-site vehicle garages, leachate storage tanks and weighbridge taken next to the vehicle garages facing north east towards



Photograph 12 – Photograph of the vehicle garages taken from the site office parking facing north east



Photograph 13 – Photograph of the permitted land falling outside the landfill site's western ownership boundary facing north west



Photograph 14 - Photograph of the permitted land falling outside the landfill site's western ownership boundary facing west



Photograph 15 – Photograph taken facing east across the permitted area to be surrendered located at the north eastern extent of Pen-y-bont Landfill site



Photograph 16 – Photograph taken facing north across the hardstanding and colliery spoil heap

