

Appendix 1

**Photographs taken on 20th March
2018 during site inspection at
Bryn Posteg Landfill
(Permit BU7766IC)**



Leachate outbreaks noticed in haul road

(Please continue to next page)



Leachate ponding around base of gas well



Landfill gas emanating from the haul road (See bubbling in haul's surface water/runoff)



Spreading of what appeared to be leachate on tipping face

Stockpiled soil (which appeared to be waste) was observed on the geomembrane and geotextile capping during our inspection

