

Synthite and TS Resins – Containment audit photos 26/06/2019



Formic acid containers stored adjacent to area of permeable surfacing



Drain position allowing surface water flows to drain to an area of permeable surfacing.



Lack of separation between stored IBCs and adjacent gravel surfacing



Ground below dripping lagoon pipework manifold



Spills in area of concrete jointing/ cracking adjacent to the tank farm



TS tank farm bund approx. 1/3rd full of rainwater



Lack of spacing between container storage and fencing adjacent to warehouse. Blue drum leaning on fence.



Concrete degraded on lower yard area adjacent to lagoon access ramp