



# DRAINAGE SOLUTIONS

A Solution For Every Problem


Job Sheet 02519

AR Drainage Solutions  
Unit 19, The Valley Enterprise  
Bedwas House Ind. Estate  
Bedwas, CF83 8GF  
Tel: 029 20885660  
www.ardrainagesolutions.com  
info@ardrainagesolutions.com

|                   |                                                                                                                                              |
|-------------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| Customer Details: | Job No. / Ref.:                                                                                                                              |
| ROA Recycling     | Client: ROA                                                                                                                                  |
| Commercial Lane   | Date: 24/04/18                                                                                                                               |
| Risca             | Time Start: 0900                                                                                                                             |
| Newport           | Time Finish: 12:45                                                                                                                           |
| NPI 6AN           | Risk Assessment <input checked="" type="checkbox"/> HPWJ <input checked="" type="checkbox"/> HPWC <input checked="" type="checkbox"/>        |
|                   | Rodded <input checked="" type="checkbox"/> Camera Used <input checked="" type="checkbox"/> Camera Survey <input checked="" type="checkbox"/> |
|                   | Excavation <input type="checkbox"/> Installed <input type="checkbox"/> Re-Instated <input type="checkbox"/>                                  |
| Tel:              | Patch <input type="checkbox"/> Liner <input type="checkbox"/> Site Cleaned <input type="checkbox"/>                                          |
| Email:            | Pipe Diameter 100 ISO Pipe Length                                                                                                            |

## Engineer / Description of Works:

Comments: Arrived on site to investigate INTERCEPTOR RUN. LOCATED CONVECTIVITY TO 2 DOWN STREAM MANHOLES MANHOLE 2 HAS WHAT FEELS TO BE SYPHON LEAVING CHAMBER TOWARDS RIVER. ALSO SYPHON LEAVING INTERCEPTOR UNABLE TO HAVE COMPLETE SURVEY BETWEEN MH1 AND MH2 LINE HOLDING DUE TO SYPHON. INFORMED THAT OUTFALL HAS FLAP VALVE THAT OVERGROWS WITH BRUSH DEBRIS AND HASN'T BEEN CLEANED IN LONG TIME.



## Recommendations:

Engineer Sign:

G. Wynn

Customer Sign:

J. Parsons

Date:

24/04/18