

RECEIVED

13 JAN 2014

For 221013

Part B - to be submitted as soon as practicable

Any more accurate information on the matters for notification under Part A.	The sampler had broken down due to water ingress (into electrical parts). The fitment attached to the external sample point broke causing water to get in.
Measures taken, or intended to be taken, to prevent a recurrence of the incident	The fitment has been fixed. The location of the external sample point has been changed.
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	No pollution caused (manual samples taken while the sampler was down)
The dates of any unauthorised emissions from the facility in the preceding 24 months.	04.01.2011, 03.06.2011, 24.07.2011, 17.09.2011, 06.07.2012, 19.08.2012, 05.09.2012, 08.01.2013, 21.07.2013, 27.07.2013

Name*	Alana Corbett
Post	Quality & Environmental Leader
Signature	
Date	13.01.2014

* authorised to sign on behalf of the operator

	INITIALS	DATE
OK FOR PUBLIC REGISTER	AS	14/1/14
COPIED TO PUBLIC REGISTER	JB	EDRM