RF01

RECEIVED
27 JUN 2013

Schedule 1 – Notification of Abnormal Emission **Page 1 of 1**

Part B – 0508

Permit Number	**BL9941**
Name of Operator	South Caernarfon Creameries Ltd (SCC Ltd)
Location of Installation	Rhydygwystl, Chwilog, Pwllheli, Gwynedd, LL53 6SB
Location of the Emission	W1-water
Time and date of the Emission	Ortho-phosphate breach @ 1.85 mg/lt during 24hrs on 12-06-13
Fax To:	**01244 548805**

Any more accurate information on the matters for modification under Part A	Dosing pipe-work repaired
Measurement taken, or intended to be taken, to prevent a recurrence of the incident.	SCC internal result for the day was 1.45mg/lt. Dosing pipe-work repaired and chemical dosing increased
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission.	Continued monitoring internally. Further adjustment and increase to chemical dosing as necessary.
The dates of any unauthorised emissions from the installation in the preceding 24 months.	N/A

*** Name:**	H G Jones
Post:	Quality Assurance Manager
Signature:	H G Jones
Date:	24-06-13

** Authorised to sign on behalf of South Caernarfon Creameries Ltd.*

RF01

INITIALS DATE
OK FOR PUBLIC REGISTER A.C 26.7.13
COPIED TO PUBLIC REGISTER JB EDRM