RECEIVED
27 NOV 2014

Schedule 1 – Notification of Abnormal Emission Page 1 of 1

# Part A – 0523

| | |
|---|---|
| **Permit Number** | **BL9941** |
| **Name of Operator** | South Caernarfon Creameries Ltd (SCC Ltd) |
| **Location of Installation** | Rhydygwystl, Chwilog, Pwllheli, Gwynedd, LL53 6SB |
| **Location of the Emission** | W1 |
| **Time and date of the Emission** | During 30 minutes on 26-11-14 |
| **Fax To:** | **01244 548805** |

| **Substance(s) emitted** | **Media** | **Best estimate of the quantity or rate of emission.** | **Time during which the emission took place** |
|---|---|---|---|
| Rate | W1 water | 10.25l/s and14.02l/s | 30 minutes |
| | | | |

| | |
|---|---|
| **Measures taken, or intended to be taken, to stop the emission.** | Surge in rate caused by BAFF blower changeover after maintenance. Ensure that level of lameella is lowered sufficiently to prevent surge when blowers are off for a prolonged period during maintenance. |

| | |
|---|---|
| *** Name:** | H G Jones |
| **Post:** | Quality Assurance Manager |
| **Signature:** | H G Jones |
| **Date:** | 27-11-14 |

** Authorised to sign on behalf of South Caernarfon Creameries Ltd.*

ENTERED ON PUBLIC REGISTER 1.C. 4.2.15
SCANNED TO PUBLIC REGISTER