RECEIVED
04 DEC 2014

RF01

**Schedule 1 – Notification of Abnormal Emission** **Page 1 of 1**

Part B – 0523

| | |
|---|---|
| **Permit Number** | **BL9941** |
| **Name of Operator** | South Caernarfon Creameries Ltd (SCC Ltd) |
| **Location of Installation** | Rhydygwystl, Chwilog, Pwllheli, Gwynedd, LL53 6SB |
| **Location of the Emission** | W1-water |
| **Time and date of the Emission** | Rate breach of 10.25l/s and 14.02 l/s for 30 minutes during 26-11-14 |
| **Fax To:** | **01244 548805** |

| | |
|---|---|
| **Any more accurate information on the matters for modification under Part A** | Ensure that procedure for opening divert valve following blower shutdown is followed after any prolonged delay. |
| **Measurement taken, or intended to be taken, to prevent a recurrence of the incident.** | As above |
| **Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission.** | As above |
| **The dates of any unauthorised emissions from the installation in the preceding 24 months.** | |

| | |
|---|---|
| *** Name:** | H G Jones |
| **Post:** | Quality Assurance Manager |
| **Signature:** | |
| **Date:** | 27-11-14 |

** Authorised to sign on behalf of South Caernarfon Creameries Ltd.*

A.C. 4.2.15