Revision 01

Schedule 5 – Notification of Abnormal Emission Page 1 of 2

Part A – 543

Permit Number	**EPR/BL9941IC**
Name of Operator	South Caernarfon Creameries Ltd (SCC Ltd)
Location of Facility	Rhydygwystl, Chwilog, Pwllheli, Gwynedd, LL53 6SB
Time and date of the detection	During 24 hours on 08-03-17

(a) Notification requirements for any activity that gives rise to an incident or accident which significantly affect the environment

Date and time of the event	
Reference or description of the location of the event	
Description of where any release into the environment took place	
Substance(s) potentially released	
Best estimate of the quantity or rate of release of substances	
Measures taken, or intended to be taken to stop any emission	
Description of the failure or accident	

(b) Notification requirement for a breach of a permit condition
To be notified immediately.

Emission point reference / source	W1	
Parameter(s)	BOD	SS
Limit	20 mg/l	30 mg/l
Measured value and uncertainty	30.1 mg/l	31 mg/l
Date and time of monitoring	During 24 hours on 08-031-17	
Measures taken, or intended to be taken, to stop the emission	The elevated results are thought to be associated with a disruption to the aeration system on the plant. The surface aerator motor on the intermediate Malgar balancing tank had broken down, and was not running. Also, there was some interruption to the BAFF aeration system as there was a bearing breakdown on one blower, rendering it inactive before the standby unit was running.	

Time periods for notification following detection of a breach of a limit

Revision 01

Schedule 5 – Notification of Abnormal Emission **Page 1 of 1**

Part B -543

Permit Number	**EPR/BL9941IC**
Name of Operator	South Caernarfon Creameries Ltd (SCC Ltd)
Location of Installation	Rhydygwystl, Chwilog, Pwllheli, Gwynedd, LL53 6SB

Any more accurate information on the matters for modification under Part A	Aerator motor and blower bearing repaired and replaced.
Measurement taken, or intended to be taken, to prevent a recurrence of the incident	Continued monitoring
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	Additional de-sludging carried out to lower BOD and SS.
The dates of any unauthorised emissions from the installation in the preceding 24 months	


*** Name:**	Gwyn Jones
Post:	Quality Assurance Manager
Signature:	
Date:	20-03-17

** Authorised to sign on behalf of South Caernarfon Creameries Ltd.*

Parameter	Notification period

(c) In the event of a breach of permit that poses an immediate danger to human health or threatens to cause an immediate significant adverse effect on the environment:

Description of where the effect on the environment was detected	
Substance(s) detected	
Confirmation of substances detected	
Date of monitoring / sampling	

*** Name:**	Gwyn Jones
Post:	Quality Assurance Manager
Signature:	
Date:	20-03-17

* *Authorised to sign on behalf of South Caernarfon Creameries Ltd.*