Prysmian Group

PRYSMIAN
Draka

5th February 2015

Matthew Kelk
NRW Chester Road
Buckley
Flintshire
CH7 3AJ

Dear Matthew,

Re: Notification of failure to comply with Permit requirements – YP3732LZ

Subsequent to my Part A notification of 5th January we reported the investigation and corrective action that was carried out to you on the 14th January.

I am now able to advise the outcome of the repeated monitoring which we arranged to be carried out after this work.

- Time, date & location of emission- Sampled 15-01-2015 at 11am at the machine LEV
- The reported emission values are:

Substance	Emission Limit value	Monitoring Result	Units
Lead	0.1	0.0012	mg/m^3
Particulate	1.0	0.29	mg/m^3

- Thus as the results show the emissions have returned to the expected levels and are within the emission limits, we conclude that the corrective actions have been adequate.
- The machine will now be returned to normal service.

Yours sincerely,

Andrew Watt
Company Quality & Environment Manager
Prysmian Cables & Systems Ltd

Prysmian Group

Prysmian Cables & Systems Ltd
Registered Office
Chickenhall Lane, Eastleigh,
Hampshire, SO50 6YU
Registered Number
No. 958507 England
www.prysmiangroup.com

Telephone
02380 295262
07971129573
Fax
02380 608600
E-mail
andrew.watt@prysmiangroup.com