



LANDFILL DISPOSAL SITE

SITE NAME: TYNYLSTON OPERATOR: DAMES BROS
SITE ADDRESS: DATE: 06/11/97 TIME: 1215
LICENCE NO: 11

KEY

Satisfactory ☒
Not Satisfactory ☒
Not inspected ☐

A Entrance

	KEY	COMMENTS
1. Site Entrance	☒	
2. Security	☒	
3. Wheel Cleaning	☒	
4. Vehicle reception	☒	
5. Office Facilities	☒	
Welfare	☒	
Documentation	☒	
Staff	☒	

DIRTY WATER PENDING UPON SITE
ENTRANCE ROADWAY. TRENCH DRAIN
BLINDED → KEEP AN EYE ON
POTENTIAL PROBLEM (MUD ON HIGHWAY) &
CLEAR TRENCH DRAIN IF REQUIRED

B Landfill Area

	KEY	COMMENTS
1. Waste Handling	☒	
2. Waste Tipping and Working Area	☒	
3. Site Engineering	☒	
4. Drainage	☒	
5. Cover Material	☒	
6. Site Roads	☒	
7. Boundary Fence	☒	
8. Gas and Leachate Management	☒	
9. Plant and Equipment	☒	
10. Unpermitted Wastes Storage	☒	

SUBSTANTIAL AMOUNT OF MINERAL
FIBRE WASTE (CLOCKWALL) DEPOSITED
ED TO BE BLENDED INTO TIPPING AREA

ONE COMPACTOR BEING REPAIRED

C Environmental Control

	KEY	COMMENTS
1. Dust, Odour, noise	☒	
2. Pests	☒	
3. Litter	☒	
4. Health and Safety	☒	
5. Emergency Equipment	☒	

D General Comments and Action Required

GENERAL COMMENTS



FORM-2



INTERNAL-1

SPECIFIC LICENCE CONDITIONS BREACHED

CONDITION No. PROPOSED COMPLIANCE DATE

Waste Regulation
Officer
Operator

wmlsir.lids.frm

Samples Taken:
Photographs Taken:
Weather Conditions:

YES/NO
YES/NO

DRY / STILL