

IR/ 20 / 01

PART A

Permit Number	BM3965IA (Variation NP3235MQ)
Location of Installation	Airbus UK, Chester Road, Broughton, Chester CH4 0DR
Time and date of detection	13/03/2021 @ 20:09

(a) Notification requirements for any malfunction, breakdown or failure of equipment or techniques, accident, or fugitive emission which has caused, is causing or may cause significant pollution

To be notified within 24hours of detection	
Date and time of the event	13/03/2021 @ 20:09
Reference or description of the location of the event	Small fire detected in the electrical cupboard of the Sub Station associated with the CHP unit @ 20:09. On-site fire crews were in attendance by 20:19 and the fire was extinguished by hand by 20:25. Root cause investigation on-going with specialist due to attend site on 18/03/21 to conduct appraisal. CHP Unit is mothballed and the sub station is now isolated in the interim.
Description of where any release into the environment took place	Stringers Manufacturing Centre CHP Plant
Substance(s) potentially released	Smoke
Best estimate of the quantity or rate of release of substances	Negligible
Measures taken, or intended to be taken, to stop any emission	Fire Extinguished using CO2
Description of the failure or accident	Suspected earthing failure, investigation ongoing.

(b) Notification requirements for the breach of a limit

To be notified within 24hours of detection	
Emission point reference / source	
Parameter(s)	
Limit	
Measured value and uncertainty	
Date and time of monitoring	
Measures taken, or intended to be taken, to stop the emission	
Time periods for notification following detection of a breach of limit	
Parameter	Notification period

(c) Notification requirements for the detection of any significant adverse environmental effect

To be notified within 24hours of detection	
Description of where the effect on the environment was detected	
Substance(s) detected	
Concentrations of substances detected	
Date of monitoring / sampling	