



Part A – 627

Permit Number	EPR/BL9941IC
Name of Operator	South Caernarfon Creameries Ltd (SCC Ltd)
Location of Facility	Rhydygwystl, Chwillog, Pwllheli, Gwynedd, LL53 6SB
Time and date of the detection	During 24 hours 14.04.21

(a) Notification requirements for any activity that gives rise to an incident or accident which significantly affect the environment

Date and time of the event	
Reference or description of the location of the event	
Description of where any release into the environment took place	
Substance(s) potentially released	
Best estimate of the quantity or rate of release of substances	
Measures taken, or intended to be taken to stop any emission	
Description of the failure or accident	

(b) Notification requirement for a breach of a permit condition
To be notified immediately.

Emission point reference / source	W1
Parameter(s)	BOD
Limit	20 mg/l
Measured value and uncertainty	21.8 mg/l
Date and time of monitoring	During 24 hours on 14.04.21
Measures taken, or intended to be taken, to stop the emission	The internal COD result of 53 mg/l and external COD result of 33.8 mg/l were not indicative of a high BOD. Due to the sample exceeding the holding time for BOD analysis, it is not possible to repeat the test on the retained sample.


Time periods for notification following detection of a breach of a limit

Parameter	Notification period

--	--

(c) In the event of a breach of permit that poses an immediate danger to human health or threatens to cause an immediate significant adverse effect on the environment:

Description of where the effect on the environment was detected	
Substance(s) detected	
Confirmation of substances detected	
Date of monitoring / sampling	

* Name:	Gwyn Jones
Post:	Quality Assurance Manager
Signature:	
Date:	23.04.21


** Authorised to sign on behalf of South Caernarfon Creameries Ltd.*

RF01


Schedule 5 – Notification of Abnormal Emission
Page 1 of 1

Part B -627

Permit Number	EPR/BL9941IC
Name of Operator	South Caernarfon Creameries Ltd (SCC Ltd)
Location of Installation	Rhydygwystl, Chwillog, Pwllheli, Gwynedd, LL53 6SB

Any more accurate information on the matters for modification under Part A	The aeration system has since been improved by incorporating two new additional aerators, which are now installed and operational. This should assist in reducing the BOD figure going forward.
Measurement taken, or intended to be taken, to prevent a recurrence of the incident	
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	Continued monitoring.
* Name:	Gwyn Jones
Post:	Quality Assurance Manager
Signature:	
Date:	23.04.21

* Authorised to sign on behalf of South Caernarfon Creameries Ltd.