SUBSTITUTION OF LEAD STABILISER REPORT 2017
REHAU LTD, AMLWCH EP PERMIT BX6421IY – CONDITION 4.1.8

Response:-

During 2015 all articles were converted from lead stabiliser to calcium zinc stabiliser. This proved to be 100% successful therefore, the requirement for lead stabiliser has ceased.
There was no lead stabiliser used during 2016 or 2017.

Corrective Action:-

There is lead stabiliser on site and there will be no future deliveries.

M Brown
17.01.19