

Bradford, Julie

From: Quick, David J (Padeswood) GBR <david.quick@hanson.biz>
Sent: 21 January 2015 14:52
To: Ross, Stuart; Quick, David J (Padeswood) GBR
Cc: Hodson, Joanne (Padeswood) GBR; Bradford, Julie
Subject: RE: Compliance Assessment Report BL1096IB/0229448

Stuart,

Thank you for the detailed CAR of 16/01/2015.

With respect to Section C Interim Measures and Site Inspection, paragraph 3, as discussed contract labour has been unable to shut the defective sand door in between loads due to the sand door driving through the limits and requiring an electrical reset by a qualified electrician. Electricians were not always available to effect the reset as quickly as we would want. As an interim measure we have installed a system that manually operates the door regardless of the situation with the limits, thus allowing the door to be shut by contractors without the intervention of an electrician.

Should you have any further queries on this issue please do not hesitate to contact me.

Regards

David

*David Quick
Plant Manager
Hanson Cement
Padeswood Works
+44 (0)7713685727*

From: Ross, Stuart [mailto:Stuart.Ross@cyfoethnaturiolcymru.gov.uk]
Sent: 16 January 2015 16:49
To: Quick, David J (Padeswood) GBR
Cc: Hodson, Joanne (Padeswood) GBR; Bradford, Julie
Subject: Compliance Assessment Report

Hi David,

Please find attached a Compliance Assessment Report following my unplanned site inspection 22/12/14 and our meeting 06/01/15.

As you will see the report is detailed and includes a number of actions for you to complete over the coming weeks / months. If you would like to discuss the report in more detail please give me call.

I will be in touch to arrange a site inspection in the coming weeks.

Regards,

Stuart Ross
Regulatory Officer 1 (PPC/RSR) / Swyddog Rheoliadol 1 (RhDP/RhSY)
Cyfoeth Naturiol Cymru / Natural Resources Wales
Ffon/Tel: 01244 894622
E-bost/E-mail
stuart.ross@cyfoethnaturiolcymru.gov.uk
stuart.ross@naturalresourceswales.gov.uk