


Schedule 6 - Notification

Part B - to be submitted as soon as practicable

Permit Number	BR9383ID	Notification Reference	EP_EX_146
Name of operator	Knauf Insulation Ltd		
Location of Facility	Chemistry Lane, Queensferry, Deeside, Flintshire, CH5 2DA		
Time and date of the detection	EP_EX_146: Day of 11th January 2015		

Any more accurate information on the matters for notification under Part A.	<p>The cause of the delay in the validation of the CEMs data for January is as described in the Part A Notification.</p> <p>The exceedance of the SO2 Daily Average limit was caused by the vibratory feeding pans over delivering on coke during several charges, which was detected via the OSI PI system.</p>
Measures taken, or intended to be taken, to prevent a recurrence of the incident	<p>The measures taken to prevent the recurrence of the data downloading issue is as described in the Part A Notification.</p> <p>Adjustments were made to the raw materials feed vibrator setting to ensure the correct set point for the charge was met.</p>
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	<p>It is believed that no permanent harm will result from the incident.</p>
The dates of any unauthorised emissions from the facility in the preceding 24 months.	<p>30/01/13, 07/02/13, 26/02/13, 11/03/13, 21/03/13, 22/03/13, 04/04/13, 07/04/13, 18/04/13, 26/04/13, 09/05/13, 21/05/13, 31/05/13, 25/06/13, 27/09/13, 04/11/13, 14/11/13, 20/11/13, 29/11/13, 04/12/13, 06/12/13, 20/01/14, 05/02/14, 12/02/14, 13/03/14, 02/04/14, 08/04/14, 21/05/14, 29/06/14, 01/07/14, 04/07/14, 11/07/14, 19/07/14, 20/07/14, 21/07/14, 8-9/10/14, 15/10/14.</p>

Name*	C. Hensley
Post	HSE Manager
Signature	
Date	23 rd February 2015

* authorised to sign on behalf of Knauf Insulation Ltd