


Schedule 6 - Notification

Part B - to be submitted as soon as practicable

Permit Number	BR9383ID	Notification Reference	EP_EX_186
Name of operator	Knauf Insulation Ltd		
Location of Facility	Chemistry Lane, Queensferry, Deeside, Flintshire, CH5 2DA		
Time and date of the detection	21 st and 22 nd October 2017		

Any more accurate information on the matters for notification under Part A.	During the subsequent planned maintenance drop shift, Engineering personnel detected a leaking seal on a cylinder, which is operated by the same compressed air system. This caused a low network pressure, which was detected by the low pressure switch. This was rectified by Knauf Insulation during that maintenance drop shift.
Measures taken, or intended to be taken, to prevent a recurrence of the incident	Engineering Department have set up a planned maintenance routine to check the pneumatic systems for the tap out arm cylinder (which was the cause of the low pressure incident).
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	It is believed that no permanent harm will result from the incident.
The dates of any unauthorised emissions from the facility in the preceding 24 months.	27/10/15, 02/02/16, 23/02/16, 15/06/16, 27/06/16, 28/06/16, 10/07/16, 15/08/16, 16/08/16, 13/09/16, 14/09/16, 25/04/2017, 24/05/17, 07/07/17, 04/08/17, 14-15/08/17, 06/09/17, 14/09/17, 16-20/09/17, 1-3/10/17

Name*	C. Keouski
Post	HSE Manager
Signature	
Date	4 th December 2017

* authorised to sign on behalf of Knauf Insulation Ltd