

Permit and introduction note: PPC regulations

Schedule 1 – Notification of abnormal emissions

Part C

Permit Number	WP3836ZF
Name of Operator	Tradebe Healthcare rnational Limited – Wrexham Clinical Waste Incinerator
Location of Installation	Wrexham

Time at which abnormal operation commenced	07:10 on 27/03/2015							
Time at which abnormal operation ceased	07:40 on 27/03							
Duration of this incidence of abnormal operation	30 minute							
Cumulative abnormal operation duration in current year (at end of present incidence)	30 minutes							
Reasons for abnormal operation	ID Fan belt failure							
How did the abnormal operation end? (e.g. plant repaired, reaching maximum permitted duration, initiation of shutdown, etc.)	New belts fitted and tension checked.							
Where the abnormal operation was caused by the failure of the particulate, CO or TOC CEM, attach a copy of the alternate monitoring data which was used to demonstrate compliance with the abnormal operation emission limit values.	New belts fitted and checked emission levels returned to below ELV							
Where abatement plant has failed, give the half-hourly average emissions for pollutants of relevance during the abnormal operation in the rows below mg/m ³								
Pollutant	1 st ½ hour	2 nd ½ hour	3 rd ½ hour	4 th ½ hour	5 th ½ hour	6 th Hour	7 th ½ hour	8 th ½ hour
HCl								
SO ₂								
CO								
NO _x								
VOC								
Dust	71.84							

Name*	Paul Phillips
Post	Assistant Plant Manager
Signature	
Date	27/03/2015

* authorised to sign on behalf of SITA Healthcare Limited, Wrexham Clinical Waste Incinerator