

May 2022

Day	Downtime	Availability	Rationale
1	0	100.00%	
2	0	100.00%	
3	0	100.00%	
4	0	100.00%	
5	0	100.00%	
6	0	100.00%	
7	0	100.00%	
8	0	100.00%	
9	0	100.00%	
10	0	100.00%	
11	0	100.00%	
12	21.5	10.42%	Plant tripped iniatlly due to Boiler Screen Fouling. Due to loss of Output primarity due to Flue Gas ducting ingress, decision taken to faciltate a mini outage to primarily repair Ducting and steam leaks.
13	24	0.00%	
14	24	0.00%	
15	24	0.00%	
16	24	0.00%	
17	24	0.00%	
18	7.5	68.75%	Restart delayed due to Profibus and Oil Burner Fault.
19	0	100.00%	
20	0	100.00%	
21	0	100.00%	
22	0	100.00%	
23	0	100.00%	
24	0	100.00%	
25	0	100.00%	
26	0	100.00%	
27	0	100.00%	
28	0	100.00%	
29	0	100.00%	
30	0	100.00%	
31	0	100.00%	
Month	149	79.97%	