

AB CONNECTORS

**Review of Fugitive Emissions
January to December 2021**

Permit Number BV7443IP

Annual Review of Fugitive Emissions

Previous 12 months January to December 2020

No fugitive emissions reported

January to December 2021

No fugitive releases reported

2021 Environmental Incident Reports

22/04/2021 Machine Shop Smoke coming from EMCO 4 Machine

Seized bearing caused excess heat leading to Nylon part melting and causing smoke

CO2 extinguisher used.

Trade effluent and Stack Emission Results 2021

Emissions to sewer and stack emissions within permitted limits

Reviews and Improvements to Further Minimise the Risk of Fugitive Emissions

- New storage facility for flammable chemicals installed
- New caged area for storage of gas bottles.
- Entry to all external doors now controlled by a card key entry system
- New bund purchased for storage of oil and coolant in the Machine shop
- Drain Protection Mats replaced



New Bund for storage of oil in Machine Shop