
Oakes, Ian

From: Baker, Keith <K.Baker@KRONOSPAN.co.uk>
Sent: 04 November 2022 13:25
Oakes, Ian
Subject: Incident Communication - 2208084
Attachments: Incident Report - Kronospan WIRS 2208084.docx; Incident Report Summary
Kronospan - 2208084.pdf

Hi Ian

In response to the odour complaint you received this morning (attached).

As discussed earlier this morning we intended to carryout quarterly emissions monitoring on the Press Abatement system today, this activity is carried out at the press abatement system emergency / short stack and not the WESP 32 stack. The emissions testing team set up their equipment and we then switched over to the short stack for the duration of the test at 09:30, the test takes up to 3 hours

We received an email complaint about odour and blue haze from***** at 10:02. On receipt of this email complaint we immediately switched from the emergency stack back to the WESP 32 stack. The odour issues and blue haze then started to improve.

Testing was planned many days in advance of the actual sampling activity to ensure that the MDF 1 & 2 and Particle Board presses were in operation.

We will reschedule the press abatement system emissions testing and ensure that prior to sampling we will only test if the wind direction and speed is favourable.

Kind regards

Keith Baker
EHS Manager

lu•onoswaom

KRONOSPAN Ltd Chirk
Wrexham LL14 5NT.

T +44 1691 775320
M +44 7795 438249

K.Baker@KRONOSPAN.co.uk <http://uk.kronospan-exoress.com/en>
www.kronospan-worldwide.com

Kronospan Limited registered in England.
Company Registration No 981905 CEO Mr. L.A. Scheibltreiter

