

| SCHEDULE 5 Notification      |                    |
|------------------------------|--------------------|
| <b>Part A</b>                |                    |
| Permit Number:               | BL7108IM           |
| Name of Operator:            | Tata Steel UK Ltd  |
| Location of Facility:        | Port Talbot Works  |
| Time & Date of the Detection | 03/05/2022: 8.00am |

| (b) Notification requirements for breach of a permit condition |                                                                                                               |
|----------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| Emission point/reference source                                | W1 Long Sea Outfall                                                                                           |
| Parameter(s)                                                   | Cyanide                                                                                                       |
| Limit                                                          | 0.1 mg/l                                                                                                      |
| Measured value and uncertainty                                 | Measured value: 0.153 mg/l<br>Monitoring uncertainty value = 0.01 mg/l based on a measured value of 0.1 mg/l. |
| Date time of monitoring, and emission value.                   | Date time of monitoring = 03/05/22<br>Adjusted result following the application of uncertainty = 0.143 mg/l.  |
| Measures taken, or intended to be taken, to stop the emission  | Investigations are ongoing as to the cause of the breach.                                                     |
| REF: S5N/22/35A                                                |                                                                                                               |