


Planned or unplanned outage of abatement equipment

Permit Number	EPR/BL7108IM
Name of operator	Tata Steel
Location of Facility	Port Talbot Steel Works
Date & time of when the planned or unplanned outage commence (Please state if planned or unplanned)	27/08/2023 @ 15:24 Unplanned

(PART A)	
Reference or description of the location of the event	A10A Fume extraction
Reason for the outage	Unplanned due to vibration causing the fan to trip
Immediate action taken to mitigate environment incident (if applicable)	Fan 3 in operation
Has the abatement equipment been reinstated? (If yes state date and time)	Yes 28/08/2023 @ 17:15
If no confirm planned date to reinstate abatement equipment	
Is further correspondence required to notify NRW that the abatement equipment has been reinstated?	No
Reference	A10A BOS 115_270823
(PART B) Any more accurate information on the matters notified under Part A (Specifically if the outage of the abatement equipment has increased)	N/A
Date abatement equipment returned to service	28/08/2023
Name	Nicola Parnell
Post	Environment Lead, UK ETS & Air Quality
Signature	
Date	31/08/2023
Reference	A10A BOS 115_280823