



Schedule 5 – Notification

Part A

Permit Number	EPR/BP 3635MR
Name of operator	Harsco Environmental
Location of Facility	Harsco Ring Fenced Site Tata Steel Port Talbot
Date reported	12 th September 2023

Date and time of incident	8 th September 2023 – 08:00 / 10:00 / 13:00										
Location	Lancing Booth										
Substance released	No release of particulates from the stack during the period of non - compliance										
Measures taken or intended to be taken to stop any emission	Awareness training regarding scrap material and its potential for emission levels. Lancing of the scrap material was aborted and left unprocessed.										
Description of the failure or accident	<p>On 3 occasions the particulate levels were recorded over 20mg/m3. On investigation it was identified that scrap material which has not been processed by Harsco since 2012</p> <p></p> <table><tr><th>Date</th><th>Max Value (INDmg/m3)</th><th>Number of failures</th><th>95% Compliance</th><th>Max < 150% Limit</th></tr><tr><td>08 Sep 23</td><td>22.99</td><td>3</td><td>FAIL</td><td>pass</td></tr></table>	Date	Max Value (INDmg/m3)	Number of failures	95% Compliance	Max < 150% Limit	08 Sep 23	22.99	3	FAIL	pass
Date	Max Value (INDmg/m3)	Number of failures	95% Compliance	Max < 150% Limit							
08 Sep 23	22.99	3	FAIL	pass							

Name	Paul Morgan
Post	EHS Manager
Signature	
Date	12/09/23