

Planned or unplanned outage of abatement equipment

Permit Number	EPR/BL7108IM
Name of operator	Tata Steel
Location of Facility	Port Talbot Steel Works
Date & time of when the planned or unplanned outage commence (Please state if planned or unplanned)	07/10/2023 @ 13:00 Unplanned

(PART A)	
Reference or description of the location of the event	Topas monitor 1380 (PM10/PM100/TSP) - Penrhyn
Reason for the outage	Monitor is recording minus figures – investigation ongoing with supplier and internally
Immediate action taken to mitigate environment incident (if applicable)	N/A
Has the abatement equipment been reinstated? (If yes state date and time)	No (this monitor is used for reporting not abatement purposes)
If no confirm planned date to reinstate abatement equipment	TBD
Is further correspondence required to notify NRW that the abatement equipment has been reinstated?	Yes
Reference	TOPAS ENV 133_071023
(PART B) Any more accurate information on the matters notified under Part A (Specifically if the outage of the abatement equipment has increased)	
Date abatement equipment returned to service	
Name	Nicola Parnell
Post	Environment Lead, Air Quality & UK ETS
Signature	
Date	23/10/2023
Reference	TOPAS ENV 133_071023

