

Surface Water Environmental Monitoring Report

Your Ref: EAWML30058 DP3733BK

3rd March 2023

PPC Team
Natural Resources Wales
Rivers House
Fortrain Road
St Mellons Business Park
Cardiff
CF3 0EY

Attn: Luke Burton

Re: EAWML30058 & DP3733BK – Docksway Disposal Site. Latest Area 1 and 2 Surface Water Monitoring Results, round 228.

This report contains the results of surface water monitoring undertaken at Docksway Disposal Site in February 2023. Included in this report are summary tables showing the sample location details (table 1) and the field test results of each sample location, (table 2).

Table 1 – Details of the sampling locations sampled during Round 228

Sample reference	Sample locations
SW1A	Upstream of the River Ebbw
SW24	Oxbow Lake
C3_Asb	Cell 3 Settling lagoon

Note: SW02 and SW07 are not monitored due to unsafe access. SW23 not sampled water level too high, level above the outlet point. SW25 and SW26 outlets were dry at time of sampling. (-) Manta failed during sampling.

Surface water quality assessment

Table 2 – Summary of the testing results during Round 228

Monitoring locations	Field temperature (°C)	Lab pH	Ammoniacal nitrogen (mg/l)	Field dissolved oxygen (%)	Biological oxygen demand (mg/l)	Suspended solids (mg/l)	Chemical oxygen demand (mg/l)
SW1A	-	8.03	0.29	-	<1	n/a	121
SW24	-	8.26	<0.2	-	7.43	n/a	43.4
C3_Asb	-	8.25	3.79	-	4.56	10.7	54

The site Environmental Monitoring Technician did not record the presence of a sheen on the surface of the water during this sampling round at C3_Asb and the laboratory did not detect any asbestos fibres in the sample. The surface water quality of C3_Asb was also within the permit limits during this round (Round 228) for the parameters tested.

Conclusion

Newport City Council (NCC) will continue to monitor the surface water quality of Docksway Disposal Site in accordance with the aftercare monitoring plan for Area 1, the Environmental Permit (Table S3.2 of the Permit), and in accordance with the relevant discharge consent limits.

If you have any questions regarding this report, then please do not hesitate to contact us.

Yours sincerely,

L. Embrey

- CC: Robert Hughes NCC (Landfill Manager)
Luke Embrey NCC (Monitoring Technician)