


### Planned or unplanned outage of abatement equipment

Permit Number	EPR/BL7108IM
Name of operator	Tata Steel
Location of Facility	Port Talbot Steel Works
Date & time of when the planned or unplanned outage commence (Please state if planned or unplanned)	20/11/2023 @ 11:00 Planned outage

<b>(PART A)</b>	
Reference or description of the location of the event	A10A Fan 3A Fume Extraction
Reason for the outage	Planned Maintenance
Immediate action taken to mitigate environment incident (if applicable)	Fan 3 remains in operation
Has the abatement equipment been reinstated? (If yes state date and time)	Yes, 23/11/2023 @ 01:00 am
If no confirm planned date to reinstate abatement equipment	
Is further correspondence required to notify NRW that the abatement equipment has been reinstated?	No
Reference	A10A BOS 141_201123
<b>(PART B)</b> Any more accurate information on the matters notified under Part A (Specifically if the outage of the abatement equipment has increased)	During maintenance manifold ducting was found holed. Time to source spares for repair.
Date abatement equipment returned to service	23/11/2023
Name	Jessica Richards
Post	Environment Officer
Signature	
Date	23/11/2023
Reference	A10A BOS 141_201123