



STRUCTURAL ENGINEERING : PROJECT MANAGEMENT

Photo Survey Report  
Parc Coed y Nant  
Cardiff  
CF23 7EZ

## **Index**

1.0. Photographs 2019

2.0. Photographs 2023

3.0. Photograph Location Plan

## 1.0 Photograph Sheets 2019



Wall from left hand side of Dam (PHOTO 1)



Wall from right hand side of Dam (PHOTO 2)



Sunken side slab (PHOTO 3)



Degree of settlement to slab (PHOTO 4)



Water holding at pond edge (PHOTO 5)



Overtopping of Dam wall (PHOTO 6)



Extraction location on Nant Glandulas (Photo 7)

## 2.0 Photograph Sheets 2023



Repaired dam coping stones and barrier (PHOTO 8)



Uncharted manhole exposed during works (PHOTO 9)

Salt Consultancy Ltd,  
Suite 17, Business Development Centre, Main Avenue, Treforest Industrial Estate, CF37 5UR  
Tel No: 01443 843413, Mobile No: 07711 593359, Email: [j.salt@saltconsultancy.co.uk](mailto:j.salt@saltconsultancy.co.uk)



Extraction point on Nant Glandulas with grille refitted (PHOTO 10)



Water level at extraction point (PHOTO 11)

Salt Consultancy Ltd,  
Suite 17, Business Development Centre, Main Avenue, Treforest Industrial Estate, CF37 5UR  
Tel No: 01443 843413, Mobile No: 07711 593359, Email: [j.salt@saltconsultancy.co.uk](mailto:j.salt@saltconsultancy.co.uk)



Grille and Manhole from Bank (PHOTO 12)



Close up of Grille fixing (PHOTO 13)

Salt Consultancy Ltd,  
Suite 17, Business Development Centre, Main Avenue, Treforest Industrial Estate, CF37 5UR  
Tel No: 01443 843413, Mobile No: 07711 593359, Email: [j.salt@saltconsultancy.co.uk](mailto:j.salt@saltconsultancy.co.uk)



Previously uncharted manhole has been raised and exposed (PHOTO 14)

### **3.0 Photograph Location Plan**

