

Daniel Durrans

From: Marine Licensing <marinelicensing@cyfoethnaturiolcymru.gov.uk>
Sent: 09 October 2018 16:17
To: Daniel Durrans
Cc: Gwyn Parry; Bryn Shiland
Subject: Q18135 -Penmaenmawr Outfall Marine Licence Enquiry

Q18135

Good afternoon Daniel,

Thank you for providing the additional information, Based on the information provided it appears the works would fall within the band 1 low risk activity criteria, we will however review this fully on receipt of the full application and supporting information.

I would remind you that a band 1 application must be supported with an email from the Maritime and Coastguard agency confirming no impact to navigation is predicted, and should recommendation be made by the MCA these should be incorporated into your method statement. You can contact them at this address

navigationsafety@mcga.gov.uk

Band 1 application forms are available to download from our website, please ensure you review the band 1 guidance fully before completing the application.

Our service level for band 1 application is 6 weeks from receipt of a complete application.

Should you have any further queries please do not hesitate to contact us

Kind regards

Pete

Peter Morrison
Swyddog Trwyddedu Morol/ Marine Licensing Officer
Cyfoeth Naturiol Cymru / Natural Resources Wales
Ffôn / Phone : 03000 65 3371
Ty Cambria, Caerdydd / Cambria House, Cardiff
Siaradwr Cymraeg

www.cyfoethnaturiol.cymru / www.naturalresources.wales

Yn falch o arwain y ffordd at ddyfodol gwell i Gymru trwy reoli'r amgylchedd ac adnoddau naturiol yn gynaliadwy.

Proud to be leading the way to a better future for Wales by managing the environment and natural resources sustainably.



Croesewir gohebiaeth yn Gymraeg a byddwn yn ymateb yn Gymraeg, heb i hynny arwain at oedi

Correspondence in Welsh is welcomed, and we will respond in Welsh without it leading to a delay

From: Daniel Durrans <daniel.durrans@conwy.gov.uk>
Sent: 09 October 2018 15:54
To: Marine Licensing <marinelicensing@cyfoethnaturiolcymru.gov.uk>
Cc: Gwyn Parry <gwyn.parry@conwy.gov.uk>; Bryn Shiland <Bryn.Shiland@conwy.gov.uk>
Subject: RE: Q18135 -Penmaenmawr Outfall Marine Licence Enquiry

Hi Pete,

Thanks for your response.

The duration of the works is 5 days and the co-ordinates of the outfall are E: 271717 N: 376641.

We have decided to amend the maintenance repair works to the following:

Method of work will be an excavator situated on the slipway to remove the outfall top slab and store. The excavator will then move the outfall back into position. If this is not possible from the slipway the excavator will undertake this from the front of the outfall. Following alignment a 300mm wide galvanised steel plate will be secured to the back of the outfall using 8no. M12 bolts. The recess for the top slab will then be cleared and the top slab reinstated. This slab will be secured using two 300mm wide galvanised steel plates with 8no. M12 bolts on each.

Specification

- 16mm Galvanised Steel Plate 300mm width
- M12 bolts 100mm long evenly spaced 50mm from outer edge with resin

Thanks again

Daniel Durrans

Technegydd Cynllunio Trwy Gymorth Cyfrifiadur / CAD Technician
Grŵp Isadeiledd a Pherygl Llifogydd / Flood Risk & Infrastructure Group
AFfC - Amgylchedd, Ffyrdd a Chyfleusterau / ERF - Environment, Roads and Facilities
Cyngor Bwrdeistref Sirol CONWY County Borough Council

✉: daniel.durrans@conwy.gov.uk

☎: 01492 575115

💻: www.conwy.gov.uk

From: Marine Licensing [<mailto:marinelicensing@cyfoethnaturiolcymru.gov.uk>]
Sent: 27 September 2018 08:42
To: Daniel Durrans <daniel.durrans@conwy.gov.uk>
Cc: Gwyn Parry <gwyn.parry@conwy.gov.uk>; Bryn Shiland <Bryn.Shiland@conwy.gov.uk>
Subject: Q18135 -Penmaenmawr Outfall Marine Licence Enquiry

Q18135

Good afternoon Daniel,

Thank you for contacting the marine licensing team. The exemption you refer to below, exemption 18 of the The Marine Licensing (Exempted Activities) (Wales) Order 2011 [here](#) , gives provision for Coast Protection

Authorities like yourselves to carry out maintenance to coast defence works, subject to condition as stated in the exemption. However the exemption only applies to Natural Resources Wales in regards to maintaining flood defence works or drainage works. Therefore as the repair is related to maintenance of an outfall, this would not be considered exempt and a marine licence would be required.

If you are able to give some additional detail regarding the method proposed including estimate duration of the works, use of concrete, and a grid reference or co-ordinates to show the location of the works I will be able to help advise whether the works may be considered under band 1 low risk activity process or whether a band 2 application will be required, there is guidance on our website on the activities that may be considered band 1 and the process and I would also ask that you review this and indicate if you consider the works fall under any of the listed activity in the guidance, if the activity does not fall within any listed in the guidance document a band 2 licence will be required

Band 1 [here](#)

Kind regards

Pete

Trwyddedu Morol/ Marine Licensing
Cyfoeth Naturiol Cymru / Natural Resources Wales

www.cyfoethnaturiol.cymru / www.naturalresources.wales

Yn falch o arwain y ffordd at ddyfodol gwell i Gymru trwy reoli'r amgylchedd ac adnoddau naturiol yn gynaliadwy.

Proud to be leading the way to a better future for Wales by managing the environment and natural resources sustainably.



Croesewir gohebiaeth yn Gymraeg a byddwn yn ymateb yn Gymraeg, heb i hynny arwain at oedi

Correspondence in Welsh is welcomed, and we will respond in Welsh without it leading to a delay

From: Daniel Durrans <daniel.durrans@conwy.gov.uk>

Sent: 25 September 2018 09:42

To: Marine Licensing <marinelicensing@cyfoethnaturiolcymru.gov.uk>

Cc: Gwyn Parry <gywyn.parry@conwy.gov.uk>; Bryn Shiland <Bryn.Shiland@conwy.gov.uk>

Subject: Penmaenmawr Outfall Marine Licence Enquiry

Hi Peter,

Please can you advise if the following is exempt from a Marine Licence: The works are to realign a broken section of outfall and secure the top slab that was previous damaged by storms earlier this year.

The photos below show the extents of the damage:



Our contractor will be undertaking the works from the slipway, if possible, or in front using an excavator to move the outfall back into position and secure a galvanised metal plate to the back. The top slab will be lifted into position and secured using dowels.

I have looked through the 'The Marine Licensing (Exempted Activities) (Wales) Order 2011' and feel the works could fall under the 'Maintenance of coast protection, drainage and flood defence works'. The outfall takes surface water from nearby streets and a car park.

If you require any further information please let me know.

Regards


Daniel Durrans

Technegydd Cynllunio Trwy Gymorth Cyfrifiadur / CAD Technician
Grŵp Isadeiledd a Pherygl Llifogydd / Flood Risk & Infrastructure Group
AFfC - Amgylchedd, Ffyrdd a Chyfleusterau / ERF - Environment, Roads and Facilities
Cyngor Bwrdeistref Sirol CONWY County Borough Council

✉: daniel.durrans@conwy.gov.uk

☎: 01492 575115

💻 www.conwy.gov.uk



Mae'r neges e-bost hon ac unrhyw ymgysylltiadau yn gyfrinachol, ac wedi eu bwriadu ar gyfer yr un sy'n cael ei h/enwi yn unig. Gallent gynnwys gwybodaeth freintiedig. Ar gyfer yr amodau llawn ynglŷn â chynnwys a defnyddio'r neges e-bost hon ac unrhyw atodiadau, gweler www.conwy.gov.uk/ebost_ymwadiad

This email and any attachments are confidential and intended for the named recipient only. The content may contain privileged information. For full conditions in relation to content and use of this e-mail message and any attachments, please refer to www.conwy.gov.uk/email_disclaimer