

23<sup>rd</sup> September 2020

Mr I Oakes  
Natural Resources Wales  
Chester Road  
Buckley  
Flintshire  
CH7 3AJ

Dear Mr Oakes

**PART B REPORT (SCHEDULE 1) – PPC PERMIT NUMBER BU 2357**

Please find enclosed the information provided as a Part B report for the following Part A notification:-

Part A ref. N°. 20/09/2020 - A

Yours sincerely  
FOR WARWICK INTERNATIONAL GROUP LIMITED



MR PETER BRYANT  
HEALTH SAFETY, ENVIRONMENT & SECURITY MANAGER

<b>TITLE :</b>	Part 'B' Report Form			<b>ISSUE NO.</b>	15.0
<b>REF :</b>	RCF20	<b>AREA:</b>	SITE	<b>DATE OF ISSUE:</b>	08.05.13
<b>RELATED DOCUMENT:</b>	WI 903 App C			<b>PAGE:</b>	2 of 2
<b>FILENAME:</b>	Part B Form 20th September 2020 noise complaint			Last printed 23/09/2020 15:21:00	



Part B Notification (schedule 1) in accordance with condition 5 (5.1.1 and 5.1.2) of PPC Permit BU 2357.

## **REFERENCES**

Part A form, Ref. N°. 20/09/2020 - A

### **Further, more accurate information on the matters for notification under Part A.**

At 22.15hrs on the 20<sup>th</sup> September the site received a call from a local resident in Rhewl. They were reporting hearing a high-pitched noise which had started about twenty minutes before the call was made and had now reduced. Whilst checks were being made on site the Shift Plant Manager left site and visited the local area. Several pieces of equipment were shutdown/re-started whilst he was off site but there did not appear to be any change to the noise heard in the village.

Back on site the Shift Plant manager checked the plant records and found that there had been a trip in Plant 6 which had shut off all services to the Plant. This involved a steam release to atmosphere to reduce the pressure in the main header. Although the timing of this was not exact this seemed to provide a possible cause for the noise, especially as the caller had said that the noise had reduced.

### **Measures taken (or intended to be taken) to prevent a recurrence of the incident.**

The caller was contacted the following day and updated with the possible explanation for the noise problem. It was requested that if there was any reoccurrence of the noise disturbance that they should mention contacting the site HSES Department. The HSES Department have committed to attending site whenever there is a local noise complaint. This will allow the HSES Department to carry out monitoring to assist in identifying what is causing the problem. The cause of the trip in Plant 6 was due to a high level in a vessel being loaded. This is not a common occurrence and will not be investigated further. Plant 6 will be shut down once the AED Recycle plant is operational, so this particular issue will no longer occur.

### **Measures taken (or intended to be taken) to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission.**

It is thought that no measurable environmental damage has occurred as a result of this incident.

### **Dates of unauthorised emissions from the installation in the previous 24 months.**

28/09/2018, July/Aug 2018, July/Aug Sept 2018, Sept/Nov/Dec 2018, July/Aug/Sept/Oct/Nov 2018, 10/04/2019, 13/06/2019, 11/09/2019, July-November 2019, September – November 2019, 01/01/2020, 02/01/2020, 08/01/2020, 01/02/2020, 03/02/2020, 18/02/2020, 30/04/2020, 12/05/2020, 12/06/2020, 11/08/2020.