

Schedule 5 - Notification

These pages outline the information that the operator must provide.

Units of measurement used in information supplied under Part A and B requirements shall be appropriate to the circumstances of the emission. Where appropriate, a comparison should be made of actual emissions and authorised emission limits.

If any information is considered commercially confidential, it should be separated from non-confidential information, supplied on a separate sheet and accompanied by an application for commercial confidentiality under the provisions of the EP Regulations.

Part A

Permit Number	GP3235GH
Name of operator	Randall Parker Foods
Location of Facility	Dolwen Abattoir
Time and date of the detection	12:00 21/02/20

(a) Notification requirements for any activity that gives rise to an incident or accident which significantly affects or may significantly affect the environment	
To be notified Immediately	
Date and time of the event	12:00 21/02/20
Reference or description of the location of the event	Plant Room
Description of where any release into the environment took place	Plant Room
Substances(s) potentially released	R404A
Best estimate of the quantity or rate of release of substances	10 kg
Measures taken, or intended to be taken, to stop any emission	Border Temperature control were contacted after routine monitoring found a problem with chiller 4 System in plant room at 12:00 on the 21/02/20 and immediately turned the unit off. He pressure tested with oxygen free nitrogen and a leak was identified on the condenser coil , 10 KG of R404A had leaked. The pipe was repaired and system refilled with to 10 kg of R404A
Description of the failure or accident.	Fractured pipe on the Condensor

(b) Notification requirements for the breach of a permit condition	
To be notified immediately	
Emission point reference/ source	Plant Room
Parameter(s)	
Limit	
Measured value and uncertainty	

Date and time of monitoring	12:00 21/02/20
Measures taken, or intended to be taken, to stop the emission	He pressure tested with oxygen free nitrogen and a leak was identified on the condenser coil , 10KG of R404A had leaked. The pipe was repaired and system refilled with to 10KG of R404A

Time periods for notification following detection of a breach of a limit	
Parameter	Notification period

(c) In the event of a breach of permit condition which poses an immediate danger to human health or threatens to cause an immediate significant adverse effect on the environment:	
To be notified immediately	
Description of where the effect on the environment was detected	
Substances(s) detected	
Concentrations of substances detected	
Date of monitoring/sampling	

Part B - to be submitted as soon as practicable

Any more accurate information on the matters for notification under Part A.	Gas loss measured and found to be 10 KG of R404A On the condenser coil
Measures taken, or intended to be taken, to prevent a recurrence of the incident	Shut down of system after condenser coil . leak was identified as a condenser coil , 10KG of R404A had leaked. The coil was repaired and system refilled with to 10KG of R404A
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	Border Temperature to continue to monitor and carry out preventative maintenance if needed
The dates of any unauthorised emissions from the facility in the preceding 24 months.	03/10/2016,3 and 4/12/2016 10/01/17, 17/01/17 / 22/02/17/ 14/03/17,16-07-17,18-08-17,6:11:17 17/1/18 08/02/18 9/5/18 15/08/2018 12/09/2018 19/06/19 04/07/19 04/10/19 20/11/19 11/02/20

Name*	Gareth Gower
Post	Technical Officer
Signature	
Date	21/02/20

* authorised to sign on behalf of the operator