

AB CONNECTORS

**Review of Fugitive Emissions
January to December 2020**

Permit Number BV7443IP

Annual Review of Fugitive Emissions

Previous 12 months January to December 2019

No fugitive emissions reported

January to December 2020

No fugitive releases reported

2020 Environmental Incident Reports

23/12/2020 Busbar fire in Plating Shop. Water ingress to tapping box causing a short in a disused tapping box. Minimal smoke and use of CO2 extinguisher to put out fire, no water. Building evacuated, CO2 extinguisher used to extinguish fire prior to arrival of the fire brigade, the fire brigade reviewed, and all electrical supplies were isolated.

Trade effluent and Stack Emission Results 2019

Emissions to sewer and stack emissions within permitted limits

Reviews and Improvements to Further Minimise the Risk of Fugitive Emissions

- New storage facility for flammable chemicals installed
- New caged area for storage of gas bottles.
- Entry to all external doors now controlled by a card key entry system
- New bund purchased for storage of oil and coolant in the Machine shop



New Bund for storage of oil in Machine Shop